

# N. M. OIL CONC. COMMISSION

Form 9-331  
May 1963)

UNITED STATES P. O. SUBMIT IN TRIPLICATE\*  
DEPARTMENT OF THE INTERIOR (Other instructions on re-  
GEOLOGICAL SURVEY verse side)

Form approved.  
BUDGET BUREAU No. 42-R1424

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL <input checked="" type="checkbox"/> GAS <input type="checkbox"/> WELL <input checked="" type="checkbox"/> WELL <input type="checkbox"/> OTHER _____	5. LEASE DESIGNATION AND SERIAL NO. NM-0556301
2. NAME OF OPERATOR Read & Stevens, Inc.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME -
3. ADDRESS OF OPERATOR P.O. Box 1518, Roswell, NM 88201	7. UNIT AGREEMENT NAME -
4. LOCATION OF WELL (Report location clearly and in accordance with State requirements.* See also space 17 below.) At surface 1980' FNL and 660' FEL	8. FARM OR LEASE NAME Federal "C" 9. WELL NO. 1
10. FIELD AND POOL, OR WILDCAT Undesignated	11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA Sec. 30-8S-36E
12. COUNTY OR PARISH Roosevelt	13. STATE NM

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
4140.5' KB

### NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/> FRACTURE TREAT <input type="checkbox"/> SHOOT OR ACIDIZE <input type="checkbox"/> REPAIR WELL <input type="checkbox"/> (Other) <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETE <input type="checkbox"/> ABANDON* <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>
--	---

### SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/> FRACTURE TREATMENT <input type="checkbox"/> SHOOTING OR ACIDIZING <input type="checkbox"/> (Other) <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> ABANDONMENT* <input checked="" type="checkbox"/>
--	---

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

12-24-82 Pull rods & pump, 102 jts 7/8" rods, 288 jts 3/4" rods, 1-2"X1 1/2"X16' RHBH Pump.

12-31-82 Set CIBP @ 9695', 61H w/tbg.

1-5-83 CIBP @ 9695' w/5sx cmt 30'. Load csg w/9#/gal mud, spot 25sx @ 8800'-8600', pull tbg out of hole.

1-6-83 Remove bit, weld on to 5 1/2" csg, cut csg @ 4000', LD 15jts.

1-7-83 LD 5 1/2" csg, total 126jts, run tbg to 4180', spot 50sx plug, pull 27 stands.

1-8-83 Tag 50sx plug @ 3782'-4180', LD tbg, weld on to 8 5/8" csg, cut 8 5/8" csg @ 1090'.

1-9-83 LD 27jts 8 5/8" csg, run tbg to 1140', spot 50sx plug.

1-11-83 Tag plug @ 985', spotted 50sx plug 1140'-985', spot 40sx plug @ 420'.

1-12-83 Tag plug @ 372', spot 50sx 372'-312', plug from 420'-312', 40sx plug @ 50' to surface w/dry hole marker.

1-12-83 We will notify USMMS when ready for inspection.

hereby certify that the foregoing is true and correct

SIGNED B. J. J. J. TITLE Drilling & Production Manager DATE 1-17-83

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_  
 CONDITIONS OF APPROVAL, IF ANY

**APPROVED**  
**PETER W. CHESTER**  
**APR 25 1986**  
 BUREAU OF LAND MANAGEMENT  
 ROSWELL RESOURCE AREA

See Instructions on Reverse Side

**RECEIVED**

JAN 20 1983

MINERAL SERVICE  
 ROSWELL, NEW MEXICO

HOBBS  
CITY OFFICE  
APR 29 1986  
RECEIVED