

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIP  
(Other instruction  
verse side)ATP\*  
1 re-Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 053510

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Alcorn Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Vada Penn

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec 26, T-8-S, R-35-E

12. COUNTY OR PARISH 13. STATE

Roosevelt

N. M.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. NAME OF OPERATOR Coquina Oil Corporation	
3. ADDRESS OF OPERATOR 418 Bldg of the Southwest, Midland, Texas 79701	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit N, 660' FSL and 1980' FWL of Sec. 26	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) GL 4171 KB 4182

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

X

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

We propose to P&amp;A as follows:

Set 25 sx cmt plug in 5 1/2 csg at 9700' (above perfs 9738-60)

Cut and pull 5 1/2" csg.

Spot 25 sx cmt plug on top of 5 1/2 stub (if above 5450) If 5 1/2 pulled from below 5450', then spot this 25 sx plug at 5450 on top Glorietta

Spot 25 sx in and out of base of 8 5/8 (at 4097')

Cut and pull 8 5/8,

Spot 35 sx on top 8 5/8 csg stub

Spot 35 sx in bottom of 13 3/8

Spot 10 sx in top of 13 3/8

Fill between plugs with mud, erect DHM.

18. I hereby certify that the foregoing is true and correct

SIGNED

JB Taylor

TITLE

Superintendent

DATE

6/24/71

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

RECEIVED

JUN 28 1971

OIL CONSERVATION COMM.  
HOBBS, N. M.