NO. OF COPIES RECEIVED		
L		Form C-103
DISTRIBUTION		Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		
U.S.G.S.		5a, Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
		L-2981
	SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS F US!	ORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR E **APPLICATION FOR PERMIT _** (FORM C-101) FOR SUCH PROPOSALS.)	
1.		7, Unit Agreement Name
OIL X GAS		
2. Name of Operator		8. Farm or Lease Name
BTA Oi	1 Producers	NM 696 Ltd.
3. Address of Operator		9. Well No.
104 So	. Pecos, Midland, Texas 79701	1
4. Location of Well		10. Field and Fool, or Wildcat
ਜ	1980 FEET FROM THE North LINE AND 1980	Wildcat-Devonian
UNIT LETTER	FEET FROM THE LINE AND	TITITITITITITITITITITITITITITITITITITI
Wast	LINE, SECTION 12 TOWNSHIP 8-S RANGE 35-E	
THE WEST	LINE, SECTION TOWNSHIP RANGE	— NMPM: (
mmmm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4158' G.L.	Roosevelt
	Check Appropriate Box To Indicate Nature of Notice, Repo	
NOT	-	EQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
7	<del>-</del> \	==
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	X PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING	COMMENCE DRILLING OPNS.  CHANGE PLANS CASING TEST AND CEMENT JQI	PEGG AND ABANDONMENT
	<del></del>	PEGG AND ABANDONMENT
	CHANGE PLANS CASING TEST AND CEMENT JQI	PEGG AND ABANDONMENT
OTHER	CHANGE PLANS CASING TEST AND CEMENT JQI	B X
OTHER  17. Describe Proposed or C  work) SEE RULE 103.	CHANGE PLANS  CASING TEST AND CEMENT JOI OTHER  Completed Operations (Clearly state all pertinent details, and give pertinent dates,	, including estimated date of starting any proposed
OTHER  17. Describe Proposed or C  work) SEE RULE 1103.	CHANGE PLANS  CASING TEST AND CEMENT JQI OTHER  Completed Operations (Clearly state all pertinent details, and give pertinent dates)  Spudded in 4 p.m. 10-26-69. Drilled 17 <sup>1</sup>	, including estimated date of starting any proposed  2" hole to 387'. Ran
OTHER  17. Describe Proposed or C  work) SEE RULE 1103.	Completed Operations (Clearly state all pertinent details, and give pertinent dates,  Spudded in 4 p.m. 10-26-69. Drilled 17 <sup>1</sup> 12 3/4" O.D. 33.38# surface casing set	, including estimated date of starting any proposed  y" hole to 387'. Ran  a) 387' w/375 sx reg.
OTHER  17. Describe Proposed or C  work) SEE RULE 1103.	CHANGE PLANS  CASING TEST AND CEMENT JQI OTHER  Completed Operations (Clearly state all pertinent details, and give pertinent dates)  Spudded in 4 p.m. 10-26-69. Drilled 17 <sup>1</sup>	, including estimated date of starting any proposed  y" hole to 387'. Ran  a) 387' w/375 sx reg.
other  17. Describe Proposed or C work) SEE RULE 1103.	Change Plans  Casing Test and Cement Journal Other  Completed Operations (Clearly state all pertinent details, and give pertinent dates,  Spudded in 4 p.m. 10-26-69. Drilled 17-  12 3/4" O.D. 33.38# surface casing set 6-  2% c.c. (Circ.) Plug down 11:15 p.m. 10-	including estimated date of starting any proposed  'a' hole to 387'. Ran  387' w/375 sx reg.  0-26-69. WOC.
other  17. Describe Proposed or C work) SEE RULE 1103.	Completed Operations (Clearly state all pertinent details, and give pertinent dates,  Spudded in 4 p.m. 10-26-69. Drilled 17 <sup>1</sup> 12 3/4" O.D. 33.38# surface casing set	including estimated date of starting any proposed  'a' hole to 387'. Ran  387' w/375 sx reg.  0-26-69. WOC.
other  17. Describe Proposed or C work) SEE RULE 1103.  10-26-69:	Completed Operations (Clearly state all pertinent details, and give pertinent dates).  Spudded in 4 p.m. 10-26-69. Drilled 17 <sup>1</sup> 12 3/4" O.D. 33.38# surface casing set @ 2% c.c. (Circ.) Plug down 11:15 p.m. 10  After WOC 18 hrs., pressure tested casing	including estimated date of starting any proposed  'a' hole to 387'. Ran  387' w/375 sx reg.  0-26-69. WOC.
other  17. Describe Proposed or C work) SEE RULE 1103.	Change Plans  Casing Test and Cement Journal Other  Completed Operations (Clearly state all pertinent details, and give pertinent dates,  Spudded in 4 p.m. 10-26-69. Drilled 17-  12 3/4" O.D. 33.38# surface casing set 6-  2% c.c. (Circ.) Plug down 11:15 p.m. 10-	including estimated date of starting any proposed  '2" hole to 387'. Ran  387' w/375 sx reg.  0-26-69. WOC.
other  17. Describe Proposed or C work) SEE RULE 1103.  10-26-69:	Change Plans  Change Plans  Casing Test and Cement Jourother  Completed Operations (Clearly state all pertinent details, and give pertinent dates,  Spudded in 4 p.m. 10-26-69. Drilled 17 <sup>1</sup> 12 3/4" O.D. 33.38# surface casing set @ 2% c.c. (Circ.) Plug down 11:15 p.m. 10  After WOC 18 hrs., pressure tested casin  Now drilling ahead.	including estimated date of starting any proposed  includ
other  17. Describe Proposed or C work) SEE RULE 1103.	Change Plans  Casing Test and Cement Journ other  Completed Operations (Clearly state all pertinent details, and give pertinent dates,  Spudded in 4 p.m. 10-26-69. Drilled 17 <sup>1</sup> 12 3/4" O.D. 33.38# surface casing set 62% c.c. (Circ.) Plug down 11:15 p.m. 10  After WOC 18 hrs., pressure tested casin Now drilling ahead.  Drilled 11" hole to 3940'. Ran 8 5/8" (	including estimated date of starting any proposed  "" hole to 387'. Ran  "387' w/375 sx reg.  "0-26-69. WOC.  "ng to 600 psi - O.K.  "O.D. 32# J-55 casing set
other  17. Describe Proposed or C work) SEE RULE 1103.  10-26-69:	CHANGE PLANS  CASING TEST AND CEMENT JOUNT OTHER  Completed Operations (Clearly state all pertinent details, and give pertinent dates).  Spudded in 4 p.m. 10-26-69. Drilled 17-12 3/4" O.D. 33.38# surface casing set 62% c.c. (Circ.) Plug down 11:15 p.m. 164  After WOC 18 hrs., pressure tested casin Now drilling ahead.  Drilled 11" hole to 3940'. Ran 8 5/8" (2003) 3940' w/2000 sx cement. Circ. to surface to surface casing the control of th	including estimated date of starting any proposed  "" hole to 387'. Ran  "387' w/375 sx reg.  "0-26-69. WOC.  "ng to 600 psi - O.K.  "O.D. 32# J-55 casing set
other  17. Describe Proposed or C work) SEE RULE 1103.  10-26-69:	Change Plans  Casing Test and Cement Journ other  Completed Operations (Clearly state all pertinent details, and give pertinent dates,  Spudded in 4 p.m. 10-26-69. Drilled 17 <sup>1</sup> 12 3/4" O.D. 33.38# surface casing set 62% c.c. (Circ.) Plug down 11:15 p.m. 10  After WOC 18 hrs., pressure tested casin Now drilling ahead.  Drilled 11" hole to 3940'. Ran 8 5/8" (	including estimated date of starting any proposed  "" hole to 387'. Ran  "387' w/375 sx reg.  "0-26-69. WOC.  "ng to 600 psi - O.K.  "O.D. 32# J-55 casing set
17. Describe Proposed or C work) SEE RULE 1103.  10-26-69:  10-27-69:	Change Plans  Change Plans  Casing test and cement Journal other  Completed Operations (Clearly state all pertinent details, and give pertinent dates).  Spudded in 4 p.m. 10-26-69. Drilled 17-12 3/4" O.D. 33.38# surface casing set 62% c.c. (Circ.) Plug down 11:15 p.m. 100  After WOC 18 hrs., pressure tested casing Now drilling ahead.  Drilled 11" hole to 3940'. Ran 8 5/8" (@ 3940' w/2000 sx cement. Circ. to surface).	including estimated date of starting any proposed  y" hole to 387'. Ran  387' w/375 sx reg.  0-26-69. WOC.  ng to 600 psi - O.K.  O.D. 32# J-55 casing set face. Plug down 6:45 p.m
17. Describe Proposed or C work) SEE RULE 1103.  10-26-69:  10-27-69:	Completed Operations (Clearly state all pertinent details, and give pertinent dates).  Spudded in 4 p.m. 10-26-69. Drilled 17¹ 12 3/4" O.D. 33.38# surface casing set @ 2% c.c. (Circ.) Plug down 11:15 p.m. 10  After WOC 18 hrs., pressure tested casin Now drilling ahead.  Drilled 11" hole to 3940'. Ran 8 5/8" (@ 3940' w/2000 sx cement. Circ. to surface casing to 1000.  After WOC 18 hrs., tested casing to 1000.	including estimated date of starting any proposed  y" hole to 387'. Ran  387' w/375 sx reg.  0-26-69. WOC.  ng to 600 psi - O.K.  O.D. 32# J-55 casing set face. Plug down 6:45 p.m
17. Describe Proposed or C work) SEE RULE 1103.  10-26-69:  10-27-69:	Change Plans  Change Plans  Casing test and cement Journal other  Completed Operations (Clearly state all pertinent details, and give pertinent dates).  Spudded in 4 p.m. 10-26-69. Drilled 17-12 3/4" O.D. 33.38# surface casing set 62% c.c. (Circ.) Plug down 11:15 p.m. 100  After WOC 18 hrs., pressure tested casing Now drilling ahead.  Drilled 11" hole to 3940'. Ran 8 5/8" (@ 3940' w/2000 sx cement. Circ. to surface).	including estimated date of starting any proposed  y" hole to 387'. Ran  387' w/375 sx reg.  0-26-69. WOC.  ng to 600 psi - O.K.  O.D. 32# J-55 casing set face. Plug down 6:45 p.m
17. Describe Proposed or C work) SEE RULE 1103. 10-26-69: 10-27-69:	Completed Operations (Clearly state all pertinent details, and give pertinent dates).  Spudded in 4 p.m. 10-26-69. Drilled 17¹ 12 3/4" O.D. 33.38# surface casing set @ 2% c.c. (Circ.) Plug down 11:15 p.m. 10  After WOC 18 hrs., pressure tested casin Now drilling ahead.  Drilled 11" hole to 3940'. Ran 8 5/8" (@ 3940' w/2000 sx cement. Circ. to surface casing to 1000.  After WOC 18 hrs., tested casing to 1000.	including estimated date of starting any proposed  y" hole to 387'. Ran  387' w/375 sx reg.  0-26-69. WOC.  ng to 600 psi - O.K.  O.D. 32# J-55 casing set face. Plug down 6:45 p.m
17. Describe Proposed or C work) SEE RULE 1103. 10-26-69: 10-27-69:	Completed Operations (Clearly state all pertinent details, and give pertinent dates).  Spudded in 4 p.m. 10-26-69. Drilled 17¹ 12 3/4" O.D. 33.38# surface casing set @ 2% c.c. (Circ.) Plug down 11:15 p.m. 10  After WOC 18 hrs., pressure tested casin Now drilling ahead.  Drilled 11" hole to 3940'. Ran 8 5/8" (@ 3940' w/2000 sx cement. Circ. to surface casing to 1000.  After WOC 18 hrs., tested casing to 1000.	including estimated date of starting any proposed  y" hole to 387'. Ran  387' w/375 sx reg.  0-26-69. WOC.  ng to 600 psi - O.K.  O.D. 32# J-55 casing set face. Plug down 6:45 p.m
17. Describe Proposed or C work) SEE RULE 1103.  10-26-69:  10-27-69:	Completed Operations (Clearly state all pertinent details, and give pertinent dates).  Spudded in 4 p.m. 10-26-69. Drilled 17¹ 12 3/4" O.D. 33.38# surface casing set @ 2% c.c. (Circ.) Plug down 11:15 p.m. 10  After WOC 18 hrs., pressure tested casin Now drilling ahead.  Drilled 11" hole to 3940'. Ran 8 5/8" (@ 3940' w/2000 sx cement. Circ. to surface casing to 1000.  After WOC 18 hrs., tested casing to 1000.	including estimated date of starting any proposed  y" hole to 387'. Ran  387' w/375 sx reg.  0-26-69. WOC.  ng to 600 psi - O.K.  O.D. 32# J-55 casing set face. Plug down 6:45 p.m
17. Describe Proposed or C work) SEE RULE 1103.  10-26-69:  10-27-69:	Completed Operations (Clearly state all pertinent details, and give pertinent dates).  Spudded in 4 p.m. 10-26-69. Drilled 17¹ 12 3/4" O.D. 33.38# surface casing set @ 2% c.c. (Circ.) Plug down 11:15 p.m. 10  After WOC 18 hrs., pressure tested casin Now drilling ahead.  Drilled 11" hole to 3940'. Ran 8 5/8" (@ 3940' w/2000 sx cement. Circ. to surface casing to 1000.  After WOC 18 hrs., tested casing to 1000.	including estimated date of starting any proposed  y" hole to 387'. Ran  387' w/375 sx reg.  0-26-69. WOC.  ng to 600 psi - O.K.  O.D. 32# J-55 casing set face. Plug down 6:45 p.m
17. Describe Proposed or C work) SEE RULE 1103. 10-26-69: 10-30-69: 10-31-69:	Completed Operations (Clearly state all pertinent details, and give pertinent dates).  Spudded in 4 p.m. 10-26-69. Drilled 17¹ 12 3/4" O.D. 33.38# surface casing set @ 2% c.c. (Circ.) Plug down 11:15 p.m. 10  After WOC 18 hrs., pressure tested casin Now drilling ahead.  Drilled 11" hole to 3940'. Ran 8 5/8" (@ 3940' w/2000 sx cement. Circ. to surface casing to 1000.  After WOC 18 hrs., tested casing to 1000.	including estimated date of starting any proposed  y" hole to 387'. Ran  387' w/375 sx reg.  0-26-69. WOC.  ng to 600 psi - O.K.  O.D. 32# J-55 casing set face. Plug down 6:45 p.m

TITLE Drilling Manager

CONDITIONS OF APPROVAL, IF ANY

11-3-69