

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0113
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR TOM BROWN, INC.	8. FARM OR LEASE NAME CITIES FEDERAL
3. ADDRESS OF OPERATOR P. O. BOX 2608, MIDLAND, TEXAS 79702	9. WELL NO. #1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FSL & 1980' FEL	10. FIELD AND POOL OR WILDCAT VADA (PENN)
14. PERMIT NO. 10-111-1029	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 29, T8S, R36E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4118' GR	12. COUNTY OR PARISH ROOSEVELT
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☒
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)	☐		☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other)	☐		☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. Reason for P&A - Depleted reserves & uneconomical to produce.
2. Set CIBP @ 9600' w/20' of cement on top (perfs 9769-85')
3. Cut & pull 4-1/2" csg @ 7000'. Spot ~~25~~ cmt. plug 7085'-6915'. Tag plug
4. Cut & pull 2000' of 8-5/8" csg. Spot 40 sx cmt 50' in & out of csg stub. Tag plug.
5. Spot 50 sx cmt from 469' to 369' (Surface shoe @ 419') Tag plug
6. Spot ~~10~~ cmt @ surface, 50' minimum
7. Hole will be loaded with mud.

additional plug: 140' cmt. plug 4070'-3930'. Tag plug.

18. I hereby certify that the foregoing is true and correct

SIGNED Cody V. Smith

TITLE PRODUCTION ENGINEER

DATE 1-20-92

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

CONDITIONS OF APPROVAL, IF ANY: as modified.

*See Instructions on Reverse Side

