

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions
reverse side)Form approved,
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0234351

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Aztec-Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Vada Penn

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

26 8S 36E

12. COUNTY OR PARISH

Roosevelt

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Tom Brown, Inc. (formerly Ne-C-Tex)

3. ADDRESS OF OPERATOR

P. O. Box 2608, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FN & 1980' FW

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4070 GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged as follows:

Set CIBP on Tubing @ 8942'.

Set cement retainer @ 5780' and squeezed casing with 200 sxs. Cement went to 5240' by Temperature Survey.

Casing collapsed @ 5800'.

Pumped 40 Sxs Plug @ 5850'.

Spotted 50 Sx plug @ 4 1/2 stub (5033')

spotted 50 Sx plug @ 8 5/8" shoe (4000')

Shot 8 5/8" casing @ 760', placed 100' plug @ stub of 8 5/8" (760')

Spotted 100' plug at shoe of surface casing (400')

Placed 10 Sx. plug in top. Installed marker.

Plugging done by Permian Basin Casing Pullers, Inc., Odessa, Texas

Plugging completed 11-30-73.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Vice President

DATE

June 7, 1974

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY: