

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-79

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REEFER OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
MURPHY OPERATING CORPORATION

Address of Operator
P. O. Drawer 2648, Roswell, New Mexico 88201

Location of Well
UNIT LETTER F 1830 FEET FROM THE North LINE AND 1980 FEET FROM
THE West LINE, SECTION 32 TOWNSHIP 7 South RANGE 36 East NEEM.

5a. Indicate Type of Lease
State ☒ Free ☐

5. State Oil & Gas Lease No.
K-3582

7. Unit Agreement Name
TODD LOWER SAN ANDRES UNIT

8. Term or Lease Name
TLSAU Sec. 32

9. Well No.
6

10. Field and Pool, or Wildcat
TODD LOWER SAN ANDRES ASSO.

12. County
Roosevelt

15. Elevation (Show whether DF, RT, GR, etc.)
4117' G.L.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPS. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOBS ☐
OTHER ☐	OTHER <u>drlg. deeper and perforated</u> ☒
PLUG AND ABANDON ☐	ALTERING CASING ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-5-85 RU PU. Nipple dn. WH. TIH & latched on to tbg. & pulled @ 62,000#. Tbg. stuck. TOH.

2-7-85 RU Gearhart Wireline Truck & TIH w/Freepoint. TOH. Tbg. stuck @ 2168'. Tbg. free @ 2164', collar @ 2162'. TIH w/collar locator & 60 grain charge. Backed tbg. off @ 2162'. TOH w/tbg. TIH w/3-7/8" overshot w/Jarvis & Accelerator sub & four 3-1/8" D.C. TOH. TIH to 2168' K.B. - tbg. fell 7' - 8' dn. hole. TOH w/overshot, could not work past 2168'. TIH w/1 jt. of wash pipe w/flat btm. shoe (cutrite on btm. of shoe) to 2168'. Turned wash pipe w/tongs to 2193' G.L. Wash pipe btm. out. TOH w/wash pipe. TIH w/overshot to 2168' K.B. Pulled 15 stands & TOH.

2-8-85 TIH w/6' 2-3/8" tbg. sub., could not screw into fish. TOH. TIH w/cutrite shoe w/wire cable, cleaned out on top of fish. TOH w/cutrite shoe. TIH w/overshot. Latched on to fish & tried to jar fish loose. Tried back overshot & TOH. RU W.L. truck & TIH w/one jt. under overshot. Made back off @ 2185'. TOH w/8 Stands.

2-9-85 TIH w/2-3/8" tbg. to 2185'. Screwed into fish & ran Freepoint to 3350' & TOH. RU spud bars w/Jarvis on W.L. TIH w/spud bars to 3782'. TOH w/spud bars. RU sandline. TIH w/one rod for Wright @ 3782' & drlgd. 2 ft. TOH w/same. RU outside shot. TIH to 700'. Tbg. free. TOH w/outside shot & 135 jts. 2-3/8" tbg. (all tbg.).

(continued on overside)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lois N. Brown TITLE Production Records DATE March 8, 1985

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT I SUPERVISOR DATE MAR 11 1985

CONDITIONS OF APPROVAL, IF ANY:

2-11-85 TIH w/four 3-1/8" D.C. w/3-7/8" bit to make D.O. Hit fill @ 4203', cleaned to 4315' G.L. TOH & checked bit (bit ran on iron approximately 2-3/8" dia.).

2-12-85 RU loggers. TIH to 2150'. TOH w/logging tool. TIH w/3-7/8" bit to 2800'. TOH w/3-7/8" bit. TIH w/3-1/8" logging tool to 2150'. TOH w/logging tool. TIH w/3-1/8" perf. gun to 1860'. TOH w/gun. TIH w/3-7/8" bit @ 4315'. No fill. TOH w/bit. TIH w/1-1/2" Gamma Ray Neutron log to 4313' G.L. to 1500'. TOH w/log (attached.) TIH w/3-1/8" dia. perf. gun to 1860'. Spud on guns wouldn't go. TOH w/perf gun.

2-13-85 TIH w/four 3-1/8" D.C. and w/134 jts. 2-3/8" J-55 tbgs. (btm. @ 4243.51'), 1.10 X 2-3/8" seat nipple, & 3' X 2-3/8" perf sub w/tap B.P. TOH. RU WH, set slips on tbgs., changed elev. & TIH w/52 5/8" rods, 109 3/4" rods, 2" X 1-1/2" X 16' pump w/6" string nipple, 1 x 8' x 3/4" sub and 16' 1-1/4" polish rod w/6' 1-1/2" liner. TOH.

2-14-85 Loaded tbgs. w/fresh water & pressured to 500 psi for 30 min. Held okay. RD PU.