

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N. M. OIL CONS. COMMISSION

P. O. BOX 198

ROOSEVELT, NEW MEXICO 88240

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Petroleum Production Management, Inc.

3. Address and Telephone No.

P. O. Box 957, Crossroads, NM 88114

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

510' FSL & 1980' FWL Sec 34, T-8-S, Rg-35-E

5. Lease Designation and Serial No.

NM4039 B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Will 693 Ltd.

9. API Well No.

3

10. Field and Pool, or Exploratory Area

Milnesand ABO

11. County or Parish, State

Roosevelt

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other commingle Milnesand ABO & Vada Penn
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Rig up workover unit, pull rods and tubing.
2. Trip in hole with Jumbo Jet Gun and perforate 9760' - 9774' with 4 shots per foot. Pull gun out of hole.
3. Pick up 5½" packer. Trip in the hole and set packer at 9700'.
4. Acidize with 1500 gallons of 20% NE/FE acid and over flush with 50 Bbls. fresh water. Release packer and pull out of hole.
5. Trip in hole with production tubing, pump and rods.
6. Put well on production.

14. I hereby certify that the foregoing is true and correct

Signed

Peter W. Chester

Title District Superintendent

Date 12-4-95

(This space for Federal or State office use)


Approved by

Conditions of approval, if any:

Title

APPROVED BY STATE

Date



Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

