## N. M. DIL CONS. COMMIS. A P. O. BOX 1980 Form approved. Budget Bureau No. 42-R1424. UNITED STATES 9**-331** 1963) DEPARTMENT OF THE INTERIOR verse side) 5. LEASE DESIGNATION AND SERIAL NO. GEOLOGICAL SURVEY NM 4039-B 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.) 7 UNIT AGREEMENT NAME WELL X OTHER 8. FARM OR LEASE NAME NAME OF OPERATOR Will 693 Ltd. Petroleum Production Management, Inc. 9. WELL NO. 3. ADDRESS OF OPERATOR Suite 200/Sutton Place Bldg. Wichita, Kansas 10. FIELD AND POOL, OR WILDCAT LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* Vada Penn 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 510' FSL and 1980' FWL, Sec. 34, T-8-S, R-35-E Sec. 34, T-8-S, R-35-E 12. COUNTY OR PARISH | 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. 4194' KB 4182' GL N.M. Roosevelt Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: REPAIRING WELL PULL OR ALTER CASING WATER SHUT-OFF TEST WATER SHUT-OFF ALTERING CASING PRACTURE TREATMENT MULTIPLE COMPLETE FRACTURE TREAT SHOOTING OR ACIDIZING ABANDONMENT\* ARANDON\* SHOOT OR ACIDIZE (Other) Progress Report CHANGE PLANS REPAIR WELL (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* 9-11-89---Moved in and rigged up well service unit and reverse circulating equipment. 9-11 through 9-19-89---Cleaned out to top of top fish at 9724' depth. Dressed out two tight spots in 5 1/2" OD casing at 6435' and 6840' using 4 1/8" OD string mill. 9-20 through 9-28-89---Cut over top of fish and washed over 40' of top fish consisting of 2 joints of 2 3/8" tubing with split bull plug on top and 3 1/2" OD lead impression block on bottom. Continuing to have trouble with bad spots in casing at 6435' and 6840' 9-29-89---Rigged down well service unit and reverse circulating equipment. Started efforts to gain BLM approval to start drilling a new well to hold lease. Will resume activities to clean out this well and restore to production sometime in the future. oregoing is tr and co rtify that 12-20-89 District Engineer DATE ン TITLE SIGNET ACCEPTED FOR RECORD (This space for Federal or State office use) PETER W. CHESTER DATE APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT

RECEIVED

JAN 11 1999

OCD HOBBS OFFICE