Form 9-331 (May 1963) D	UN ^T D STAT EPARTMEN I OF THE		(Other Instructions	Form appro Budget Bur 5. LEASE DESIGNATION	eau No. 42-R1424	
GEOLOGICAL SURVEY				NM-4039-A		
	Y NOTICES AND REP for proposals to drill or to deep "APPLICATION FOR PERMIT-			6. IF INDIAN, ALLOTTI	EE OR TRIBE NAME	
I. OIL GAS WELL WELL	OTHER	<u> </u>		7. UNIT AGREEMENT N	AME	
2. NAME OF OPEBATOR				8. FARM OR LEASE NA	8. FARM OR LEASE NAME	
ROGER C. HANKS OF COMPANY 3. ADDRESS OF OPERATOR C/O HODDS Pipe & Supply, Box 2010, Hobbs, N. M. 88240 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. ⁶ See also space 17 below.) At surface Unit F, 1980' FNL & 1980' FWL				Peggy	9. WELL NO.] 10. FIELD AND POOL, OR WILDCAT Vada Penn 11. SEC., T., B., M., OR BLK. AND SURVEY OR ABEA	
				9. WELL NO.		
				1 10. FIELD AND POOL,		
				11. SEC., T., B., M., OR		
					12. COUNTY OF PARISH 13. STATE	
14. PERMIT NO.	15. ELEVATIONS (Sho	15. ELEVATIONS (Show whether DF, RT, GR, etc.)		Roosevelt		
<u></u>					I <u>N.M.</u>	
16.	Check Appropriate Box To	Indicate Natu	re of Notice, Report, or	Other Data		
NOTI	CE OF INTENTION TO:		SUBSI	QUENT REPORT OF:	UENT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	·	WATER SHUT-OFF	BEPAIRING	WDLL	
FRACTURE TREAT	MULTIPLE COMPLETE	- x -	FRACTURE TREATMENT	ALTERING		
SHOOT OR ACIDIZE	ABANDON®		SHOOTING OR ACIDIZING	ABANDONM	ENT.	
REPAIR WELL (Other)	CHANGE PLANS		(Other) (Norg: Report resu	its of multiple completion npletion Report and Log f	1 on Well	
4. Spot a 35 sx p 5. Spot a 35 sx p 6. Spot a 50 sx p 7. Spot a 50 sx p 8. Spot a 50 sx p	id-laden fluids. fom approximately 700 lug @ 5-1/2" casing lug from 5300-5400'. lug in and out of ba lug at stub of 8-5/8 lug in and out of ba lug @ top & erected	stub. ase of int B" casing, ase of sur	approx. 1000'. face casing, 4017			
18. I hereby certify that the SIGNED (This space for Federal APPROVED BY CONDITIONS OF APPR	···· / · · · · · · · · · · · · · · · ·	TITLE TITLE	Agent APPRO Reverse Side ARTHUR R. DISTRICT E	DAIN	7/27/73	
	*See	Instructions of	ARTHUR R.	BROWN		