

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions
verse side)B*
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0559815-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Koch Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Bluitt San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

21-28-38E

12. COUNTY OR PARISH

Roosevelt

13. STATE

New Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. NAME OF OPERATOR Delaware-Apache Corporation	
3. ADDRESS OF OPERATOR 1700 Wilco Bldg. Midland, Texas 79701	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 535' FWL, Sec. 21	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) Gr. 3996'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data:

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

TA

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

Temp. ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9-8-70 Ran Neutron PDC Log, PBTD 4830.

Perforated 4784-4785; 4790-4801; 4805-4812; 4816-4821; Set. pkr 4823'.

Acidized /with 3000 gals 15% DS-30 acid. Swabbed well thru 9-12-70.

Reacidized w/ 10,000 gals 15% reactrol retarded acid followed by 82

lbs weakbrine treated w/5 gals surfactant. Swabbed acid water, no show.

9-17-70 Set pkr at 4557'. Re-perforated 4732-34; 4742-46; acidized w/ 3000 gals 15% acid. Swabbed acid water plus formation water, small show of gas, no oil. Swabbed thru 9-20-70.

Delaware-Apache Corporation requests temporary abandonment approval for the above well for approximately one (1) year.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Clerk

DATE 9-30-70

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

OCT 1 1970

*See Instructions on Reverse Side
U.S. GEOLOGICAL SURVEY
HOBBBS, NEW MEXICO

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1969-O-685229

847-485

RECEIVED

ENT- C 1970
OIL CONSERVATION COMM.
APR 10 1970