

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Isleamar Apache Corporation	8. Farm or Lease Name Atlantic State
3. Address of Operator P. O. Box 1772, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> , <u>350</u> FEET FROM THE <u>S</u> LINE AND <u>1980</u> FEET FROM THE <u>1</u> LINE, SECTION <u>35</u> TOWNSHIP <u>8-N</u> RANGE <u>3-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Hobbs-Penn
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set Bridge Plug at 9650', 35' Cement on top of bridge plug.
2. 100' Plug at 4471'. Cut off 5 1/2".
3. 100' Plug at 4000'.
4. Cut off 8-5/8" with 100' Plug at 1870'.
5. 100' Plug at 400'.
6. 10 sacks at surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Chap. Baker

TITLE Agent

DATE 7-14-72

APPROVED BY John W. Runyan

TITLE Agent

DATE JUL 1974

CONDITIONS OF APPROVAL, IF ANY: