

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-1107
7. Unit Agreement Name
8. Farm or Lease Name Superior State <i>Com</i>
9. Well No. 1
10. Field and Pool, or Wildcat Todd San Andres, NW
12. County Roosevelt

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator PENNZOIL COMPANY
3. Address of Operator P.O. Drawer 1828, Midland, Texas 79702-1828
4. Location of Well UNIT LETTER <u>L</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>8</u> TOWNSHIP <u>7-S</u> RANGE <u>35-E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4252 GR

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PROPOSED PLUGGING PROCEDURE

Est Dates

12/15/81 RU pulling unit. Pull tbg. Set 8-5/8" CIBP @ 4201' (30' above top to perfs).  
Dump 35' cmt on top.  
12/16/81 Run Freepoint & shoot 8-5/8" csg (should be near TOC @ 1530'). Pull csg.  
12/17/81 RIH w/tbg & circ hole w/mud (25#/bbl salt gel in 10# brine). Spot 75 sx cmt across 8-5/8" stub (50' in, 50' out). Pull up to 400' & spot 75 sx cmt across 11-3/4" surface pipe shoe (50' in, 50' out).  
12/18/81 Pull up to surface & spot 10 sx cmt. Install marker & clean up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jess Dullberg TITLE Operations Engineer DATE 11/18/81  
Orig. Signed by Jess Dullberg  
APPROVED BY Tom J. Sayer TITLE  DATE   
CONDITIONS OF APPROVAL, IF ANY: