

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-041-20328
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-2303
7. Lease Name or Unit Agreement Name Amoco "36" State
8. Well No. 1
9. Pool name or Wildcat Vada <i>Wildcat Rte</i>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4251.5' KB

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Manticore Resources
3. Address of Operator 200 N. Loraine Suite 1230 Midland, TX 79701	4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>36</u> Township <u>8 South</u> Range <u>34 East</u> NMPM <u>Roosevelt</u> County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-29-93

Move in and rig up 55 Well Service Pulling Unit. Pick up 2 7/8" tubing and go in hole open-ended.

4-30-93

Tag at 1500'. Rig up Halliburton and wash down to 1650'. Circulate hole with mud containing 25#/bbl gel. Plug as Follows:  
Plug #1: 1415'--1650' w/ 75 sx. Class "C" Plug Dn @ 10:30 AM 4-30-93  
Plug #2: 450'--300' w/ 50 sx. Class "C" Plug Dn @ 1:00 PM 4-30-93  
Wait 3 hrs and tagged plug at 305'.  
Plug #3: 60' -- Surface w/ 10 sx. Class "C". Plug Dn @ 2:45 PM 4-30-93

Cutoff wellhead, install regulation dry hole marker, cut off anchors, fill and level pits and cellar. Location ready for final inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gene Lee TITLE Agent DATE 5-5-93  
TYPE OR PRINT NAME Gene Lee TELEPHONE NO. 622-7355

(This space for State Use)

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE JUL 13 1993

CONDITIONS OF APPROVAL, IF ANY:

7-9-93