

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-041-20328

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

V-2303

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Manticore Resources

3. Address of Operator

200 N. Lorraine Suite 1230 Midland, TX 79701

7. Lease Name or Unit Agreement Name

Amoco "36" State

8. Well No.

1

9. Pool name or Wildcat

Vada Wildcat Abo

4. Well Location

Unit Letter E : 1980' Feet From The North Line and 660' Feet From The West Line

Section 36

Township 8S

Range 34E

NMPM

Roosevelt

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4251.5' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☒

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-15-92 thru 11-3-92:

Move in and rig up pulling unit and reverse equipment. Weld on head and nipple up BOP. Drill cement plugs from 0--30', 300-352', and clean out open hole down to 1558'. Tag top of 8 5/8" casing stub. Dress off 8 5/8" casing stub and tie casing together back to surface. Go in hole with 7 7/8" bit and clean out to 1562', then milled on junk. Recovered wireline and junk. Go back in hole with bit and clean out to 1591'. Had more open hole and junk. Shut down and wait on rotary rig.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Gene Lee

TITLE

Agent

DATE

11-7-92

TYPE OR PRINT NAME

Gene Lee

TELEPHONE NO. 622-7355

(This space for State Use)

DISTRICT 1 SUPERVISOR

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY

TITLE

DATE

JUL 12 1993

CONDITIONS OF APPROVAL, IF ANY:

622-7355 11-7-92 158'