	(
NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMM	C-102 and C-103 ISSION Effective 1-1-65
FILE		
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
		1T-4059
IDO NOT USE THIS FOR PROP	Y NOTICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT I ON FOR PERMIT - " (FORM C-101) FOR SUCH PERPOSALS.)	RESERVOIR.
		7. Unit Agreement Name
OIL GAS WELL	OTHER.	
2. Name of Operator		8. Farm or Lease Name
Hytech Energy Corpor	ration (Formerly Western State Produ	cing Co.) Amoco "36" State
. Address of Operator		9. Well No.
710 Western United L	ife Building $\gamma / 2 = \ell (r + r) S$.	
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER E 6	560 FEET FROM THE West LINE AND 19	80 Vada (Penn.)
• • • • • • • • • • • • • • • • • • • •		
THE North LINE, SECTION	N 36 TOWNSHIP RANGE	34-Е
THE LINE, SECTION	N TOWNSHIP RANGE	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4251.5 КВ	Roosevelt
	PLUG AND ABANDON REMEDIAL WORK	SUBSEQUENT REPORT OF:
TEMPORARILY ABANDON	COMMENCE DRILLIN	IG OPNS.
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND C	EMENT JOB
	OT HER	
OTHER	L_J	
	erations (Clearly state all pertinent details, and give pertine	ent dates, including estimated date of starting any proposed
work) SEE RULE 1103.		
3000 psi. Holdin 2. 2-19-73 - Shot 5 3. Ran tb 4. Spotte 5. Raisec	owco EZ Drill retainer at 6516'. Sq ng press. 2000 psi _{to} 1000 psi. 5-1/2" csg. at 4506! Laid down csg. og. to 4550', loaded hole with mud. ed 50 sx. plug at 4550'.	
 6. 2-20-73 - Shot 8 Perf. 7. Spotte 8. Spotte 9. Spotte 10. 2-23-73 - Covere 10cati 11. 4-11-73 Took contine 	8-5/8" csg @ 2035' & attempted to pu 2 holes @ 1300'. Had circulation. ed 50 sx cement plug at 1500', pulle ed 75 sx cement plug at 430'. Pulle ed 10 sx cement plug at surface. ed surface pipe w/welded plate. Ins	Ill. Stretched 9". Would not loose Cut at 1523'; csg. free. ed 46 jts. ed and laid down bal. csg. stalled dry hole marker, cleaned stall temp. gap in fence, haul fence
6. 2-20-73 - Shot 8 Perf. 7. Spotte 8. Spotte 9. Spotte 10. 2-23-73 - Covere 10cati 11. 4-11-73 Took c cattle out to	8-5/8" csg @ 2035' & attempted to pu 2 holes @ 1300'. Had circulation. ed 50 sx cement plug at 1500', pulle ed 75 sx cement plug at 430'. Pulle ed 10 sx cement plug at surface. ed surface pipe w/welded plate. Ins ion. down fence, removed cattleguard, ins eguard to yard. Backfilled waste pi o dry and clean up.	ad 46 jts. ed and laid down bal. csg. stalled dry hole marker, cleaned stall temp. gap in fence, haul fence it. Leveled tank battery area, cut
6. 2-20-73 - Shot 8 Perf. 7. Spotte 8. Spotte 9. Spotte 10. 2-23-73 - Covere 10cati 11. 4-11-73 Took c cattle out to	8-5/8" csg @ 2035' & attempted to pu 2 holes @ 1300'. Had circulation. ed 50 sx cement plug at 1500', pulle ed 75 sx cement plug at 430'. Pulle ed 10 sx cement plug at surface. ed surface pipe w/welded plate. Ins ion. down fence, removed cattleguard, ins eguard to yard. Backfilled waste pi o dry and clean up.	<pre>ill. Stretched 9". Would not loose Cut at 1523'; csg. free. ed 46 jts. ed and laid down bal. csg. stalled dry hole marker, cleaned stall temp. gap in fence, haul fence it. Leveled tank battery area, cut </pre>

.