

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG 1287

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dry Hole	7. Unit Agreement Name
2. Name of Operator Cactus Drilling Corporation of Texas	8. Farm or Lease Name Kewanee State
3. Address of Operator P. O. Box 2068, Hobbs, New Mexico 88240	9. Well No. #3
4. Location of Well UNIT LETTER E , 1980 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 9 TOWNSHIP 7 RANGE 35 NMPM.	10. Field and Pool or Wildcat Dakota San Andres Gas Pool
15. Elevation (Show whether DF, RT, GR, etc.) 4240 G. L.	12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

In accordance with verbal authority from Mr. Joe D. Ramey, work of plugging and abandoning referenced well started 24 May, 1972, and was completed 26 May, 1972. Plugging was performed in the following manner:

Set 10 Sacks Plug 4182 - P.S.T.D. To 4060
Cut off 4 1/2 Casing at 3,000 Ft.
Set 25 Sacks Plug at 3050 - 2940
Set 40 Sacks Plug at 1850 - 1750
Set 60 Sacks Plug at 430 - 330
Set 10 Sacks Plug 30 Ft. to Surface

Set Marker

The location should be ready for inspection within 60 days from date.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Geo. W. Pappe TITLE Vice - President DATE 14 June, 1972

APPROVED BY Nathan E. Clegg TITLE OIL & GAS INSPECTOR DATE AUG 9 1972

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 14 1972

OIL CONSERVATION COMM.
HEEDS, N. M.

8996 10

CTO-8