16.

## UNITED STATES THE INTERIOR (Other instructions or

SUBMIT IN TRIPLICATE!

Form appreved. Pudget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NM 0534316

GEOLOGICAL SURVEY							
SUNDRY	NOTICES	AND	REPORTS	ON	WELLS		

this form for proposals to arill or to deepen or plug back to a different reservoir.

(Lo not use this io	Use "APPLICATION FOR PERMIT—" for such proposals.)			
1.  OIL GAS WELL WELL	OTHER	7. UNIT AGRÉEMENT NAME		
2. NAME OF OPERATOR	J OTHER	8. FARM OR LEASE NAME		
Pierce & Dehlinger		Union Federa		
3. ADDRESS OF OPERATOR		9. WELL NO.		
815 Petroleu	m Bldg.	1		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		Vada Penn  11. sec., T., E., M., OR BLK. AND		
510' FSL & 1	980' FEL	Sec. 34, T-8-S, R-34-E		
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OF PARISH 13. STATE ROOSEVELT New Mexico		

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NCTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:		
	_			
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING	
PHACTURE TREAT	_		ABANDONMENT*	
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONNENT	
REPAIR WELL	CHANGE PLANS	(Other)(Note: Report results of mu	!tiple completion on Well	
(Other)		Completion or Recompletion B	leport and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

This well was plugged & abandoned as follows:

- 35 sx. cement @ 4500'; tagged top of plug @ 3975'. 1.
- 5 1/2" csg. cut & pulled at 3977'. 2.
- Spotted 35 sx. in & out of 5 1/2" csg., bottom of plug @ 3980'.
- 8 5/8" csg. cut & pulled at 1055'. 4.
- Set 100' plug 1070-970', 70 sx. plug. 5.
- Set 100' plug 450-350', 70 sx. plug. 6.
- Set 10 sx. surface plug: 7.
- Hole filled with mud between plugs; 10-18-75.

8. I hereby certify that the foregoing is true and correct SIGNED Recky Widdleton Ti	ITLE	Production Clerk	DATE	2-31-75
(This space for Federal of State office use)			<del> </del>	
APPROVED BY	ITLE	a i	- DATE	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,