

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.

--

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input checked="" type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Ted Weiner Oil Properties & Century Petroleum, Ltd.		8. Farm or Lease Name A.E. Lewis, et al
3. Address of Operator 1616 Oil & Gas Bldg., Ft. Worth, Texas 76102		9. Well No. 1.
4. Location of Well UNIT LETTER <u>B</u> <u>660'</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>8</u> TOWNSHIP <u>8S</u> RANGE <u>38E</u> NMPM.		10. Field and Pool, or Wildcat Bluitt San Andres Assoc
15. Elevation (Show whether DF, RT, GR, etc.) 3980.8 GR		12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work proposed as follows:

Move in and rig up rig.

Set plugs as follows:

100' plug @ 4800'
100' plug @ top of San Andres
100' plug @ base of salt
100' plug @ top of salt
100' plug in and out of the surface pipe
@ 350'

Ten sack plug @ surface.

Above work to be commenced upon securing rig.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Larry Lydick TITLE General Partner DATE May 13, 1975

Orig. Signed by

Joc D. Ramey

Dist. I, Supv.

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: