

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM - 12025

6. IF INDIAN, ALLOTTEE OR TRIBE-NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CSO-Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Bluitt(Wolfcamp)Gas

11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA

Sec. 28, T-7S, R-37E

12. COUNTY OR PARISH

Roosevelt

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

H. L. BROWN, JR.

3. ADDRESS OF OPERATOR

P.O. Box 2237, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

990' FSL & 990' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4067.4 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

COMPLETED ABANDONMENT AS FOLLOWS:

Set CIBP with 35' of cement at 8050'
Set CIBP with 35' of cement at 6600'
Mud Hole
Cut and pull 4-1/2" casing from 6416'
Place 30 sks(100') cement at 5100'
Place 35 sks (100') cement at 3770'
Cut and pull 8-5/8" casing from 716'
Place 35 sks (100') at 720 to 620'
Place 60 sks (100') at 565 to 465'
Place 10 sks (12') at 12' to 0
Installed dry hole marker.
Work completed 12-4-75.

18. I hereby certify that the foregoing is true and correct

SIGNED

Jack R. McGraw

TITLE

Drilling & Production Mgr

DATE

December 18, 1975

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

APPROVED
MAY 14 1976
ARTHUR L. BROWN
DISTRICT DIRECTOR