

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

P. O. BOX 1303  
HOBBS, NEW MEXICO 88401

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Read & Stevens, Inc.

3. Address and Telephone No.

P. O. Box 1518 Roswell, New Mexico 88202

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FNL & 2080' FEL  
Sec. 28 T7S-R35E

5. Lease Designation and Serial No.  
LC-068124

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Holly Federal #1

9. API Well No.

30-041-20433

10. Field and Pool, or Exploratory Area

Upper  
Todd San Andres

11. County or Parish, State

Roosevelt NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other \_\_\_\_\_
- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Read & Stevens proposes to plug the subject well as follows:.

- 1) Set a <sup>140'</sup>~~100'~~ cmt plug from 4,128' <sup>3980'</sup>~~4,028'~~ at the top of the San Andres perfs. *Tag plug.*
- 2) Cut and pull the 8 5/8" csg @ 3,000'. Set a 100' cmt plug from 3,050'-2,950' @ the 8 5/8" csg stub. *Tag plug.*
- 3) Set a <sup>120'</sup>~~100'~~ plug at the top of the Rustler from ~~2,100'~~ <sup>2,080'</sup> 2030'-1910'.
- 4) Set a 100' cmt plug in the base of the surface csg from 370'-270'. Set a 10 sx surface plug. *Tag plug.*
- 5) Install dry hole marker.

All plugs will be set w/ tbg and tagged, all fluid will be 9# per gallon mud laden fluid.

14. I hereby certify that the foregoing is true and correct

Signed John C. Maxey, Jr.

Title Petroleum Engineer

Date 12/4/92

(This space for Federal or State office use)

Approved by \_\_\_\_\_

Conditions of approval, if any: as modified

Title \_\_\_\_\_

APPROVED  
Date PETER W. CHESTER

DEC 14 1992

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side

BUREAU OF LAND MANAGEMENT  
ROSWELL RESOURCE AREA