

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR MURPHY OPERATING CORPORATION	8. FARM OR LEASE NAME Cone Federal
3. ADDRESS OF OPERATOR P. O. Drawer 2648, Roswell, New Mexico 88201	9. WELL NO. 4
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FEL, 1980' FSL Unit I	10. FIELD AND POOL, OR WILDCAT Tomahawk San Andres
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 31, T-7S, R-32E
15. ELEVATIONS (Show whether DP, RT, GR, etc.) 4496' GL	12. COUNTY OR PARISH Roosevelt
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) remedial work

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 12-27-84 RU PU. Unseat pump. TIH & TOH w/rods. Dropped Standing Valve dn. tbg. & loaded tbg. w/water & press. up to make hole in tbg. bigger. RU tbg. elev. & TIH & TOH w/tbg. looking for hole in tbg. TIH & TOH w/10 stands, press. up on tbg. @ 700 psi. TIH w/1 std. check. Had press. loss in collar. TOH & changed collar. Tbg. would not press. up.
- 12-29-84 TIH & TOH w/10 stnds. Tbg. would not press. up. RU sand line w/overshot & TIH w/same & fished standing valve. TOH w/tbg. to check seat nipple. TIH w/tbg., press. up & tbg. would not press. up. TOH w/tbg. & looked for leak. Standing valve went bad.
- 12-31-84 RU pipe tester & TIH, testing tbg. @ 5000 psi. Found 7 bad collar leaks. Layed dn. 6 jts. of tbg. Thread washed out. Set slips & RU WH, changed elev. & TIH w/2 X 1 1/2" X 12' RWB pump, 171 3/4" rods, 2' 3/4" rod sub & 16' polish rod w/8' 1-1/2" liner. TOH & RD. Well pumping w/good pump action.

18. I hereby certify that the foregoing is true and correct

SIGNED

Lois N. Brown
Lois N. Brown

TITLE

Production Records

DATE

FEB 25 1985

APPROVED BY

ACCEPTED FOR RECORD
PETER W. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 1 1985

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side

RECEIVED
MAR - 6 1985
C.C.R.
HOBBS OFFICE