CAPY TO C. C. C. Form approved. Budget Bureau No. 42-R1424. Form 9-331 (May 1963) UNITED STATES SUBMIT IN TRIPLICATES DEPARTMENT OF THE INTERIOR (Other instructions on re-5. LEASE DESIGNATION AND SERIAL NO. NM-17233 GEOLOGICAL SURVEY 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT" for such proposals.) 7. UNIT AGREEMENT NAME WELL X GAS WELL OTHER 8. FARM OR LEASE NAME NAME OF OPERATOR Langley Federal SUNDANCE OIL COMPANY 3. ADDRESS OF OPERATOR 9. WELL NO. Suite 510, 1776 Lincoln St., Denver, CO 80203

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface 10. FIELD AND POOL, OR WILDCAT Tomahawk San Andres
11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA 2310' FSL and 1980' FEL Unit J Section 30, T7S, R32E 12. COUNTY OR PARISH | 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. 4415' GL Roosevelt New Mexico Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: REPAIRING WELL PULL OR ALTER CASING WATER SHUT-OFF TEST WATER SHUT-OFF ALTERING CASING FRACTURE TREATMENT MULTIPLE COMPLETE FRACTURE TREAT ABANDON MENT* SHOOTING OR ACIDIZING ABANDON* SHOOT OR ACIDIZE SET PRODUCTION CASING CHANGE PLANS REPAIR WELL (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIFE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details; and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent o this work.)* Drilled to TD of 4290'. Ran Schlumberger Sidewall Neutron Porosity and Dual Laterolog

Micro-SFL logs. Ran 107 jts. $4\frac{1}{2}$ ", 10.5#, K-55 casing. Set at 4290'. Cemented with 300 sx 50/50 Pozmix mixed with 2% gel, $\frac{1}{4}\#$ floseal, 8# salt. Plug down 10:45 p.m. 10/23/78. Pressured to 1250#, okay. PBTD 4250'. Released rotary tools. WOCU.

18. I hereby certify TITLE Vice President, SIGNED <u> Richard O. Dimit</u> (This space for Federal or State office use) TITLE APPROVED BY CONDITIONS OF APPROVAL, IF ANY: *See Instructions on Reverse Sign