(August 1999)	UNI			
	DEPARTM	TED STATES 'T OF THE INTERIO		FORM APPROVED
		LAND MANAGEMEN	т N.M. 🖓	E : 11 1 20 2020
	20112/10 01		1625 N.	Expires November 30, 2003
		AND REPORTS ON	WELLS Hopps.	NM 88240
	Do not use this form for		re-enter an	LC-068124
a	bandoned well. Use For	rm 3160-3 (APD) for suc	ch proposals.	6. If Indian, Allottee or Tribe Name
				N/A
				7. If Unit or CA/Agreement, Name and/or N
SUBMIT	IN TRIPLICATE - C	ther Instructions	on reverse side	 N/A
Type of Well				8. Weil Name and No.
Oil Well	Gas Well	Other		L. Harris Federal #2
Name of Operator			······································	9. API Well No.
Yates Petroleum Co	orporation			30-041-20474
3a Address 3b. Phone No. (include area code) 105 S. 4th Street - Artesia, NM 88210 505-748-1471			10. Field and Pool, or Exploratory Area	
Location of Well (Footage, Se		505-748-1471	· · · · · · · · · · · · · · · · · · ·	Todd Wolfcamp
1980' FNL and 1980' FEL				11. County or Parish, State
ection 22-T7S-R35E				
				Roosevelt Co., NM
12. CHECK A	PPROPRIATE BOX(E	S) TO INDICATE NAT	URE OF NOTICE, REPC	ORT, OR OTHER DATA
			TYPE OF ACTION	
Notice of Intent	XAcidize	Deepen	Production (Start/Resume	
Subsequent Report	X Alter Casing	Fracture Treat		Well Integrity
Final Abandonment Notice	Casing Repair	New Construction	Recomplete	Add perforations to existing zone
	Change Plans	Plug and Abandon	Temporarily Abandon	
	Convert to Injection	Plug Back	Water Disposal	
			arting date of any proposed work and	approximate duration thereof. If the proposal is to deepen
directionally or recomplete horizor or provide the Bond No. on file will completion or recompletion in a ner reclamation, have been completed 2/6/02 - MIRU pulling unit 2/7/02 - Perforated WolfdAcidized new perfs 7666-Swab tested. $2/11/02 - Set CIBP$ at 759 2/12/02 - Rig down and reWell is SI waiting on furth $F/FEGFFF = Sub FWelf is SI waiting on furthF/FEGFFF = Sub FI hereby certify that the foregoingName (Printed/Typed)Susan Herpin$	ntaily, give subsurface locations ar th BLM/BIA. Required subsequent ewinterval, a Form 3160-4 shall of d, and the operator has determined t. amp 7666-7684' with 38 h .7684' and existing perfs 7 .7684' and existing perfs 7 .700'. Capped with 35' cem- elease all equipment. her orders. M = M + M + M + M	In the measured and true vertical determinants in the filed within 30 of the filed within 30 of the filed once testing has been could that the site is ready for final in the site is ready for final in the files, .42". 7609-7621' with 900 gals ent.	aning date of any proposed work and pths of all pertinent markers and zone lays following completion of the involv mpleted. Final Abandonment Notices specificn) 20% IC HCL.	es. Attach the Bond under which the work will be performed ed operations. If the operations results in a multiple shall be filed only after all requirements, including
directionally or recomplete horizor or provide the Bond No. on file will completion or recompletion in a ner reclamation, have been completed 2/6/02 - MIRU pulling unit 2/7/02 - Perforated WolfdAcidized new perfs 7666-Swab tested. $2/11/02 - Set CIBP$ at 759 2/12/02 - Rig down and reWell is SI waiting on furth $F/IEGAIC = Sub DiMarthin, GaintI hereby certify that the foregoingName (Printed/Typed)$	ntaily, give subsurface locations ar th BLM/BIA. Required subsequent ewinterval, a Form 3160-4 shall of d, and the operator has determined t. amp 7666-7684' with 38 h .7684' and existing perfs 7 .7684' and existing perfs 7 .700'. Capped with 35' cem- elease all equipment. her orders. M = M + M + M + M	In the measured and true vertical determinants in the filed within 30 of the filed within 30 of the filed once testing has been could that the site is ready for final in the site is ready for final in the files, .42". 7609-7621' with 900 gals ent.	Title	es. Attach the Bond under which the work will be performed ec operations. If the operations results in a multiple shall be filed only after all requirements, including
directionally or recomplete horizor or provide the Bond No. on file wit completion or recompletion in a ner reclamation, have been completed 2/6/02 - MIRU pulling unit 2/7/02 - Perforated Wolfc Acidized new perfs 7666- Swab tested. 2/11/02 - Set CIBP at 759 2/12/02 - Rig down and re Well is SI waiting on furth <i>FIEGLACE</i> Sub <i>I</i> <i>Well is SI waiting on furth</i> <i>FIEGLACE</i> Sub <i>I</i> <i>I</i> hereby certify that the foregoing Name (<i>Printed/Typed</i>) Susan Herpin	ntally, give subsurface locations ar th BLM/BIA. Required subsequent ewinterval, a Form 3160-4 shall of d, and the operator has determined t. amp 7666-7684' with 38 h 7684' and existing perfs 7 90'. Capped with 35' cem- elease all equipment. her orders. M = M + M + M M = M + M + M is true and correct	In the measured and true vertical determinants shall be filed within 30 diversified and true vertical determinants shall be filed within 30 diversified and the site is ready for final in the site is ready for final i	aning date of any proposed work and pths of all pertinent markers and zone lays following completion of the involv mpleted. Final Abandonment Notices specificn) 20% IC HCL.	Attach the Bond under which the work will be performed ec operations. If the operations results in a multiple shall be filed only after all requirements, including 2002 4.4.4.2.2.02 hnician
directionally or recomplete horizor or provide the Bond No. on file will completion or recompletion in a ner reclamation, have been completed 2/6/02 - MIRU pulling unit 2/7/02 - Perforated WolfcAcidized new perfs 7666-Swab tested. $2/11/02 - Set CIBP$ at 759 2/12/02 - Rig down and reWell is SI waiting on furth $F/1000 - Sub TWell is SI waiting on furthF/1000 - Sub TI hereby certify that the foregoingName (Printed/Typed)Susan Herpin$	ntally, give subsurface locations ar th BLM/BIA. Required subsequent ewinterval, a Form 3160-4 shall of d, and the operator has determined t. amp 7666-7684' with 38 h 7684' and existing perfs 7 90'. Capped with 35' cem- elease all equipment. her orders. M = M + M + M M = M + M + M is true and correct	In the measured and true vertical determinants shall be filed within 30 diversified and true vertical determinants shall be filed within 30 diversified and the site is ready for final in the site is ready for final i	arting date of any proposed work and pths of all pertinent markers and zone lays following completion of the involv mpleted. Final Abandonment Notices specificn) 20% IC HCL.	Attach the Bond under which the work will be performed ec operations. If the operations results in a multiple shall be filed only after all requirements, including 2002 4.4.4.2.2.02 hnician
directionally or recomplete horizor or provide the Bond No. on file will completion or recompletion in a ner reclamation, have been completed 2/6/02 - MIRU pulling unit 2/7/02 - Perforated Wolfc Acidized new perfs 7666- Swab tested. 2/11/02 - Set CIBP at 759 2/12/02 - Rig down and re Well is SI waiting on furth FIEGA Sub / Well is SI waiting on furth FIEGA Sub / March Sub / Sugan Herpin Signeture Approved by Conductors of approval, if any, are	ntally, give subsurface locations ar In BLM/BIA. Required subsequent ewinterval, a Form 3160-4 shall o d, and the operator has determinent. amp 7666-7684' with 38 h 7684' and existing perfs 7 20'. Capped with 35' cem- elease all equipment. Her orders. MI - MMC - MI - MMC	In measured and true vertical de the reports shall be filed within 30 d the filed once testing has been co d that the site is ready for final in holes, .42". 7609-7621' with 900 gals ent. <i>D</i> _C - <i>i L</i> ₁ <i>A</i> ₂ <i>CUT IN A</i> ₂ <i>SPACE FOR FEDE</i> does not warrant or cert.fy that	arting date of any proposed work and pths of all pertinent markers and zone lays following completion of the involve mpleted. Final Abandonment Notices specificm) 20% IC HCL. 20% IC HCL. Title Engineering Tec Date RAL OR STATE OFFI	Attach the Bond under which the work will be performed ec operations. If the operations results in a multiple shall be filed only after all requirements, including 2002 2002 hnician

BECENED.

2002 FEE 28 AM 8: 43



.