

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
N. M. SUBMIT IN TRIPLEX
(Other instructions on re-
verse side)
HOBBS, NEW MEXICO 88240

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

3. LEASE DESIGNATION AND SERIAL NO.

NM-15019

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Cone Federal

9. WELL NO.

10

10. FIELD AND POOL, OR WILDCAT

Tomahawk San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 30, T-7S, R-32E

12. COUNTY OR PARISH

Roosevelt

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
MURPHY OPERATING CORPORATION

3. ADDRESS OF OPERATOR
P. O. Drawer 2648, Roswell, New Mexico 88202-2648

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Unit Ltr. N, 660' FSL, 1901' FWL, Sec. 30, T-7S, R-32E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4403' GL, 4415' KB

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1/19/88 1. Pull rods, pump and tubing.

to

1/25/88 2. Squeeze existing San Andres P-2 zone perforations (4107-4151) with 500 sacks Class C cement.

3. Drill out.

4. Perforate San Andres P-3 zone from 4222-4234 and acidize with 5000 gallons 15% NeFe.

5. Perforate San Andres P-2 zone from 4107-4151, isolate zone and acidize with 4000 gallons 15% NeFe.

6. Perforate San Andres P-1 zone from 4047-4052, isolate zone and acidize with 2000 gallons 15% NeFe.

7. Run tubing rods and pump, return to production.

19. I hereby certify that the foregoing is true and correct

SIGNED

Melinda K. Hickman

TITLE Production Clerk

DATE 1/19/88

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
PETER W. CHESTER
DATE

JAN 22 1988

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA