

DIRECTIONS TO:

Westall Federal #1
Tomahawk San Andres Field
Roosevelt County, New Mexico

From KENNA, New Mexico

1. Go south on caliche road (only south road out of Kenna) for 8 miles to Sundance Oil Co. sign for Tomahawk Field.
2. Turn left and follow main caliche road for 5.2 miles.
3. Turn left at Wolfson Oil Co. No. 2 Mountain-Fed. which is on the right hand side of road.
4. Go 1200' to location.