

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 065510

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Frank

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Todd

11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA

Sec. 22, T-7-S, R-35-E

12. COUNTY OR PARISH

Roosevelt

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole

2. NAME OF OPERATOR

Ralph Nix

3. ADDRESS OF OPERATOR

P.O. Box 617, Artesia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

2310' FSL & 1980' FWL of Sec. 22, T-7-S, R-35-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4205' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7/2/80 through 7/9/80

1. Set 25 sacks of cement, plug 7505 - 7615
2. Hole full of good mud
3. Cut 4 1/2" casing off at 4826 and pulled.
4. Set 25 Sacks of cement, plug 4836-4876
5. Set 25 Sacks of cement, plug at 4826. Filled hole with water, stayed loaded.
6. Set 25 Sacks of cement, plug at 3660 - 3765, across 8 5/8" cement shoe.
7. Set 35 Sacks of cement, plug at 2,100.
8. Set 15 Sacks, surface plug.
9. Installed regulation dry hole marker
10. Released rig
11. Will notify when location is ready for inspection.

RECEIVED
SEP 5 1980
U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

RECEIVED
SEP 18 1981

U. S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Operations Manager

DATE 7/29/80

(This space for Federal or State office use)

APPROVED BY (Orig. Sgd.) PETER W. CHESTER
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

SEP 25 1981

FOR

JAMES A. GILLMAN* See Instructions on Reverse Side
DISTRICT SUPERVISOR