

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 065510

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL ☒ WELL GAS ☐ WELL OTHER ☐

2. NAME OF OPERATOR

Ralph Nix

3. ADDRESS OF OPERATOR

P. O. Box 617, Artesia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

2310' FSL and 1980' FWL, Section 22, T-7-S, R-35-E

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

FRANK

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Todd

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 22: T-7-S, R-35-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4205' GR

12. COUNTY OR PARISH

Roosevelt

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETION ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☒SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4/4/80 Rigged up unit and pulled rods and pump.

4/7/80 Pulled out of hole with tubing, went in hole with packer on tubing, setting packer at 7520'. Ran tracer survey which showed all fluid going in lower perforations at 7627'-34'.

4/8/80 Pulled packer and went in hole with Howco SVEZ Drill Retainer, set retainer at 7615'.

4/9/80 Treated well with 4000 gallons of 20% NEFE acid at a rate of 3.8 bbls per minute with a maximum pressure of 1100#. ISIP - 400#, 5 minute vacuum.

4/10/80 Swab back load with slight show of oil and gas. Recovered 60 bbls of load and well swabbed dry.

4/11/80 Ran tubing, pump and rods. Set well up to pump.

RECEIVED

APR 18 1980

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Operations Manager

DATE 4/17/80

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

DATE

APR 25 1980

U.S. GEOLOGICAL SURVEY
LOS WELLS, NEW MEXICO

*See Instructions on Reverse Side