STATE OF NEW MEXICO.

ENERGY AND MINERALS DEPARTMENT

	-
POLYDBIRYZIG	
SANTA FE	
FILE	
U.\$.G.\$.	
LAND OFFICE	
0000	

us. or (orite acctives	OIL CONSERVATION DIVISION	
DISTRIBUTION	P. O. HOX 2088	Form C-103 -
SANTA FE	SANTA FE, NEW MEXICO 87501	
FILE	31 33 34 35 37 30 1	
U.\$.g.\$,		5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5, State Off & Gas Lease No. LH 1870
CI WOO	VALOTICES AND DEPONDS OF THE STATE OF	
IDD NOT USE THIS FURNITION FOR	Y NOTICES AND REPORTS ON WELLS POSALS TO DAILL OR TO DELPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. ON FOR PERMIT JULIFORM C-1011 FOR SUCH PROPOSALS.	
OIL GAS WELL	OTHER- P&A	7. Unit Agreement Name
ame of Operator		8. Farm or Lease Name
Yates Petroleum Corpo	oration	Gulf XE State
ldress of Operator		9. Well No.
207 South 4th St., Ar	rtesia, NM 88210	1
ocation of Well		10. Field and Pool, or Wildean
	660 V	
UNIT LETTER	660 FEET FROM THE North LINE AND 1980 FEET	NW Todd SA
THE West	N 20 TOWNSHIP 7S RANGE 35E	Man Allillillilli
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4261' GR	Roosevelt
Check A	appropriate Box To Indicate Nature of Notice, Report of	or Other Data
NOTICE OF IN	TENTION TO: SUBSEQ	UENT REPORT OF:
FORM REMEDIAL WORF	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
=		ALTERING CASING
PORARILY ABANDON	COMMENCE DRILLING OPHS.	ALTERING CASING PLUG AND ABANDOFMENT X
PORM REMEDIAL WORF	COMMENCE DRILLING OPNS. CHARGE PLANS CASING TEST AND CEMENT JOS	₹ ;==
PORARILY ABANDON L OR ALTER CASING	COMMENCE DRILLING OPHS.	₹ ≒
PORARILY ABANDON	COMMENCE DRILLING OPNS. CHARGE PLANS CASING TEST AND CEMENT JOS	₹ ;==
PORARILY ABANDON OR ALTER CASING THER	COMMENCE DRILLING OPNS. CHARGE PLANS CASING TEST AND CEMENT JQS OTHER	PLUG AND ABANDOFMENT X
PORARILY ABANDON L OR ALTER CASING	COMMENCE DRILLING OPNS. CHARGE PLANS CASING TEST AND CEMENT JOS	PLUG AND ABANDOFMENT X
PORABILY ABANDON L OR ALTER CASING OTHER Describe Proposed or Completed Ope	COMMENCE DRILLING OPNS. CHARGE PLANS CASING TEST AND CEMENT JQS OTHER	PLUG AND ABANDOFMENT X
PORABILY ABANDON OR ALTER CASING THER Proposed or Completed Ope	COMMENCE DRILLING OPNS. CHARGE PLANS CASING TEST AND CEMENT JQS OTHER	PLUG AND ABANDORMENT
PORARILY ASANDON OR ALTER CASING OTHER Describe Proposed or Completed Ope	COMMENCE DRILLING OPNS. CHARGE PLANS CASING TEST AND CEMENT JQS OTHER	PLUG AND ABANDOFMENT X
PORABILY ABANDON OR ALTER CASING THER DESCRIBE Proposed or Completed Operator SEE RULE 1103.	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQS OTHER Protions (Clearly state all pertinent details, and give pertinent dates, inc	PLUG AND ABANDORMENT
THER Proposed or Completed Operately SEE RULE 1103. 2-14-85. Plugged and abandoned	change plans Commence officeing opens. casing test and cement 193 other erations (Clearly state all pertinent details, and give pertinent dates, inc	PLUG AND ABANDOMMENT X
PORABILY ABANDON L OR ALTER CASING DITHER Describe Proposed or Completed Openork) SEE RULE 1103. 2-14-85. Plugged and abandoned	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQS OTHER Protions (Clearly state all pertinent details, and give pertinent dates, inc	PLUG AND ABANDOHMENT X
PORABILY ASAMDON OR ALTER CASING THER Proposed or Completed Operative Size Rule 1103. 2-14-85. Plugged and abandoned Circulate hole w/190	commence officing opens. change plans casing test and dement and other other crotions (Clearly state all pertinent details, and give pertinent dates, included the state of the state o	PLUG AND ABANDOMMENT X
romanity agambon Then	commence officing opens. change plans casing rest and dement and other other crotions (Clearly state all pertinent details, and give pertinent dates, included the state of the state o	PLUG AND ABANDOMMENT X
romanity agambon Then	commence officing opens. change plans casing rest and dement and other other crotions (Clearly state all pertinent details, and give pertinent dates, included the state of the state o	PLUG AND ABANDOMMENT X
PORABILY ABANDON ON ALTER CASING THER PESCRILE Proposed or Completed Operators) SEE RULE 1103. 2-14-85. Plugged and abandoned Circulate hole w/190 Plug #1: 4090-3990' Plug #2: 1875-1750' Plug #3: 486-386'	commence officeing opens. change plans casing rest and cement Job other erations (Ciearly state all pertinent details, and give pertinent dates, inc well as follows: bbls gelled H ₂ O, spot cement plugs as follow w/35 sx Class "C" cement w/35 sx Class "C" cement w/35 sx Class "C" cement	PLUG AND ABANDOPMENT X
PORMALLY ABANDON THER PROPORTION Proposed or Completed Operation of Secretary Proposed Operation of Secret	commence officeing opens. change plans casing rest and cement Job other erations (Ciearly state all pertinent details, and give pertinent dates, inc well as follows: bbls gelled H ₂ O, spot cement plugs as follow w/35 sx Class "C" cement w/35 sx Class "C" cement w/35 sx Class "C" cement	PLUG AND ABANDOMMENT X
PORABLLY ABANDON OR ALTER CASING THER PROPORTED Proposed or Completed Operators, SEE RULE 1103. 2-14-85. Plugged and abandoned Circulate hole w/190 Plug #1: 4090-3990' Plug #2: 1875-1750' Plug #3: 486-386'	commence officing opens. change plans casing rest and dement and other other crotions (Clearly state all pertinent details, and give pertinent dates, included the state of the state o	PLUG AND ABANDOMMENT X
PORABLLY ASSANDON ON ALTER CASING THER PROPORED OF COMPleted Operation of SEE RULE 1703. 2-14-85. Plugged and abandoned Circulate hole w/190 Plug #1: 4090-3990' Plug #2: 1875-1750' Plug #3: 486-386' Plug #4: Surface	commence officeing opens. change plans casing rest and cement Job other erations (Ciearly state all pertinent details, and give pertinent dates, inc well as follows: bbls gelled H ₂ O, spot cement plugs as follow w/35 sx Class "C" cement w/35 sx Class "C" cement w/35 sx Class "C" cement	PLUG AND ABANDOMMENT X
PORABLLY ABANDON OR ALTER CASING THER Describe Proposed or Completed Operation SEE RULE 1703. 2-14-85. Plugged and abandoned Circulate hole w/190 Plug #1: 4090-3990' Plug #2: 1875-1750' Plug #3: 486-386' Plug #4: Surface	commence officeing opens. change plans casing rest and cement Job other livel as follows: bbls gelled H ₂ 0, spot cement plugs as follow w/35 sx Class "C" cement	PLUG AND ABANDOMMENT X
PORABLLY ASSANDON ON ALTER CASING THER PROPORED OF COMPleted Operation of SEE RULE 1703. 2-14-85. Plugged and abandoned Circulate hole w/190 Plug #1: 4090-3990' Plug #2: 1875-1750' Plug #3: 486-386' Plug #4: Surface	commence officeing opens. change plans casing rest and cement Job other livel as follows: bbls gelled H ₂ 0, spot cement plugs as follow w/35 sx Class "C" cement	PLUG AND ABANDOMMENT X
PORABLLY ABANDON OR ALTER CASING THER Describe Proposed or Completed Operation SEE RULE 1703. 2-14-85. Plugged and abandoned Circulate hole w/190 Plug #1: 4090-3990' Plug #2: 1875-1750' Plug #3: 486-386' Plug #4: Surface	commence officeing opens. change plans casing rest and cement Job other livel as follows: bbls gelled H ₂ 0, spot cement plugs as follow w/35 sx Class "C" cement	PLUG AND ABANDOMMENT X
PORABLLY ASSANDON ON ALTER CASING THER PROPORED OF COMPleted Operation of SEE RULE 1703. 2-14-85. Plugged and abandoned Circulate hole w/190 Plug #1: 4090-3990' Plug #2: 1875-1750' Plug #3: 486-386' Plug #4: Surface	commence officeing opens. change plans casing rest and cement Job other livel as follows: bbls gelled H ₂ 0, spot cement plugs as follow w/35 sx Class "C" cement	PLUG AND ABANDOMMENT X
PORABLLY ASSANDON ON ALTER CASING THER PROPORED OF COMPleted Operation of SEE RULE 1703. 2-14-85. Plugged and abandoned Circulate hole w/190 Plug #1: 4090-3990' Plug #2: 1875-1750' Plug #3: 486-386' Plug #4: Surface	commence officeing opens. change plans casing rest and cement Job other livel as follows: bbls gelled H ₂ 0, spot cement plugs as follow w/35 sx Class "C" cement	PLUG AND ABANDOMMENT X
PORABILY ASAMDON OR ALTER CASING Describe Proposed or Completed Operators, SEE RULE 1103. 2-14-85. Plugged and abandoned Circulate hole w/190 Plug #1: 4090-3990' Plug #2: 1875-1750' Plug #3: 486-386' Plug #4: Surface	commence officeing opens. change plans casing rest and cement Job other livel as follows: bbls gelled H ₂ 0, spot cement plugs as follow w/35 sx Class "C" cement	PLUG AND ABANDOMMENT X
PORABLLY ASSANDON ON ALTER CASING THER PROPORED OF COMPleted Operation of SEE RULE 1703. 2-14-85. Plugged and abandoned Circulate hole w/190 Plug #1: 4090-3990' Plug #2: 1875-1750' Plug #3: 486-386' Plug #4: Surface	commence officeing opens. change plans casing rest and cement Job other livel as follows: bbls gelled H ₂ 0, spot cement plugs as follow w/35 sx Class "C" cement	PLUG AND ABANDOMMENT X

ly that the information above is true and complet	te to the best of my knowledge and belief.	
into Doo dlett	Production Supervisor	DATE 2-15-85
chief Griffin	OIL & GAS INSPECTOR	DATE 64-17-85

