

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <u>Dry Hole</u>	7. Unit Agreement Name
2. Name of Operator <u>CITIES SERVICE COMPANY</u>	8. Farm or Lease Name <u>Turner E Com</u>
3. Address of Operator <u>P. O. BOX 1919 Midland, Texas 79702</u>	9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>F</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>17</u> TOWNSHIP <u>7S</u> RANGE <u>37E</u> N.M.P.M.	10. Field and Pool, or Wildcat <u>Und. Siluro-Dev.</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4079' GR</u>	12. County <u>Roosevelt</u>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- T.D. 8378' Rhyolite. This well was plugged and abandoned in the following manner:
1. RIH w/open ended drill pipe to T.D. and C & CH for 15 hrs.
 2. Displaced a 50 sack cement plug @ 8378-8228' across the Siluro-Devonian Zone. LDDP to 6728'.
 3. Displaced a 50 sack cement plug @ 6728-6578', across the ABO Zone. LDDP to 5078'.
 4. Displaced a 50 sack cement plug @ 5078-4928', across the Glorieta Zone. LDDP to 3575'.
 5. Displaced a 50 sack cement plug @ 3575-3425', 1/2 in and 1/2 out of 8-5/8" casing shoe @ 3500'. LDDP.
 6. Cut off 8-5/8" casing @ 300' and pulled casing.
 7. RIH w/open ended drill pipe to 2750' and displaced a 100 sack cement plug @ 2750-2450'. LDDP to 400'.
 8. Displaced a 100 sack cement plug @ 400-300' 1/2 in and 1/2 out of 13-3/8" casing shoe @ 359'. LDDP.
 9. Dumped a 10 sack cement surface plug @ 20-0'.
 10. Installed a 4" dry hole marker to designate a plugged and abandoned location.

N.M.O.C.D. was notified but did not witness plugging.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Elmer Startz</u>	TITLE <u>Reg. Oper. Mgr.-Production</u>	DATE <u>12-30-81</u>
APPROVED BY <u>Al H. Santasiewicz</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>MAY 25 1982</u>
CONDITIONS OF APPROVAL, IF ANY:		