

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-041-20617
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER SWD	7. Lease Name or Unit Agreement Name State SWD
2. Name of Operator Devon Energy Corporation (Nevada)	8. Well No. #1
3. Address of Operator 20 North Broadway Suite 1500 Oklahoma City, OK 73102	9. Pool name or Wildcat Tucker Ranch SWD; SA
4. Well Location Unit Letter B : 660 Feet From The north Line and 1980 Feet From The east Line Section 16 Township T7S Range R33E NMPM Roosevelt County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4400'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 1/18/94, we commenced operations to plug and abandon this well. We cut-off the bolts, removed the wellhead and tagged out of the hole with the tubing and packer. The next day, we tagged in the hole with the tubing to 3845'. We mixed and pumped 70 sx of Class "C" cement. The next day, we tagged in the hole with the tubing to 3508' and tagged the top of the cement plug. We tagged out of the hole with the tubing to 60'. We mixed and pumped 15 sx Class "C" cement. We shutdown for 4 days to wait on cement. On 1/25/94, we cut the head, installed the dry hole marker and cleaned location. The location has been inspected by OCD personnel.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Debby O'Donnell TITLE Engineering Technician DATE 3/21/94
(405)
TYPE OR PRINT NAME Debby O'Donnell TELEPHONE NO. 552-4511

(This space for State Use)

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE APR 14 1994
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR 21 1994

U.S. DEPARTMENT OF
OFFICE