


This may be a double  
with a side outlet



NOTE: IT IS RECOMMENDED THAT THE CHOKE LINE BE ATTACHED  
ABOVE THE BOTTOM PREVENTER

RECEIVED

APR 9 1982

G.C.D.  
HOBBS OFFICE