

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. DRINK DESIGNATION AND SERIAL NO.

LC - 065510

6. IF APPLICABLE, ALLEGED OR TITLE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposal to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Pace Exploration Company, Inc.

3. ADDRESS OF OPERATOR

P.O. Box 588, Artesia, N.M. 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State regulations.*
See also space 17 below.)
At surface

660'N 1780'E

7. LAND ACQUISITION NAME

8. FARM OR LEASE NAME

Yates Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA

Sec. 17-T7S-R35E

14. PERMIT NO.

15. ELEVATIONS (SHOW WHETHER AT, OR, ETC.)

KB 4253.2 GL 4240.2

12. COUNTY OR PARISH 13. STATE

Roosevelt N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☒
FRACTURE TREATMENT ☐	MULTIPLE COMPLETION ☐
SHUT-IN OR ACIDIZE ☐	ABANDON* ☒
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHUT-IN OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PROPOSED:

*
Perfs 4273' - 4298', plug 50' below or TD to 50' above.
Pull 3300' casing or free point depth, put plug 50'
above and 50' below stub. 100' plug at base salt @
2378'; 100' plug at top of salt at 1018'; 100' plug
base of 8 5/8" casing @ 432'; 100' plug at surface.
Attach dry hole marker at surface. Level pits and
clean location.

* Tag plug

18. I hereby certify that the foregoing is true and correct

SIGNED Peter W. Chester TITLE Operator

DATE January 29, 1985

(This space for Federal or State office use)

APPROVED BY PETER W. CHESTER
SPECIAL AGENT IN CHARGE

TITLE DATE

FEB 25 1985

See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA