

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.M.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ For ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO ENTER OR RE-ENTER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO FORM C-101 FOR SUCH PROPOSALS.)

6. Unit Agreement Name	7. Form or Lease Name
Oil Well ☒ Gas Well ☐ OTHER ☐	Tucker
Name of Operator Wallace Oil & Gas, Inc.	8. Well No. 1
Address of Operator 50 Penn Place, Suite 850, OKC, OK 73118	9. Field and Pool, or wildcard W. Tucker Ranch Canyon
Location of Well UNIT LETTER <u>K</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>5</u> TOWNSHIP <u>7S</u> RANGE <u>33E</u> NMPM.	10. County Roosevelt
11. Elevation (Show whether DF, RT, GR, etc.) Gr. 4409', KB 4430'	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☒	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	
		X OTHER <u>Acid & Frac job</u>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/21/84 Acidized w/ 2,000 gals 20% LST acid, dropped 28 ball sealers. Swabbing back load, no shows.
2/22/84 Swabbed back load, no shows.
2/23/84 Shut well in for 1 week for pressure build up. Waiting on Frac job.
3/2/84 Frac job: 12,000 gals of Thix, 12,000# 20-40 sand. Swabbed well, no shows.
3/3/84 Shut in for pressure build up.
3/5/84 SITP 320#. Swabbed well dry.
3/6/84 Tripped out of hole w/ 29 joints tubing, laid down packer. Put in Double collar 8' tubing sub, 1.1' SN. WIH w/ 132 joints of tubing, set at 4250' KB Set 10' above perms. Swabbed well dry. Shut down and released rig at 5:00 P.M.
3/7/84 Shut well in. Waiting on evaluation. Zone too tight, non-productive.

Waiting on evaluation.

13. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Secretary</u>	DATE <u>1/13/86</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>DISTRICT SUPERVISOR</u>	DATE <u>JAN 16 1986</u>
CONDITIONS OF APPROVAL, IF ANY:		