Carl Start - Printer Charles All Start Charles	DEPARTMENT	
DISTRIBUTION	P. O. BOX 2088	Form C-103 Revised 19-1-78
SANTA FE	SANTA FE, NEW MEXICO 87501	KEVIS20 19-1-70
FILE		5a. Indicate Type of Lease
U.S.G.S.		State Fee X
LAND OFFICE		5. State Oil & Gas Lease No.
OPERATOR		
OO NOT USE THIS	SUNDRY NOTICES AND REPORTS ON WELLS FORM FOR PROPOSALS TO DRILL OR TO DELPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. SE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
	а — С. L ОТНЕЯ-	
ume of Operator		8. Farm or Lease Name
	Gas. Inc.	Tucker
Wallace Oil &		9. Well No.
50 Penn Place	, <u>Suite 850, Okla. City, OK 73118</u>	1
ocation of Well	, Buile 050, Okta. Oley, Ok /9110	10. Field and Fool, or Wildcat
v	, 1980 FEET FROM THE South LINE AND 1980 FEET FR	Wildcat
UNIT LETTER	,PEET FROM THEUULII LINE ANDPEET FR	
West	LINE, SECTION 5 TOWNSHIP 7S RANGE 33E NMI	
THE WESL	LINE, SECTION TOWNSHIP 10 RANGE JJL NM	
mmmm	15. Elevation (Show whether DF, RT, GR, etc.)	12, County
	Gr. 4409', KB 4430'	Roosevelt ()))))
NO	Check Appropriate Box To Indicate Nature of Notice, Report or Contract Subseque	INT REPORT OF:
	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PORM REMEDIAL WORK	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PORARILY ASANDON	CHANGE PLANS CASING TEST AND CEMENT JOB	
L OR ALTER CABING		
CTHER		
Describe Proposed or work) SEE RULE 110	Completed Operations (Clearly state all pertinent details, and give pertinent dates, includ 9.	ing estimated date of starting any proposed
2/9/84	Reached TD at 9574'.	
2/12/84	Ran DST #1 9420' to 9574'.	
2/13/84	Ran DST $#2$ 8974' to 9106'.	
2/13/04	Kall DS1 #2 6974 LO 9100 .	
2/14/84	Set Plug at 9400' to 9300', cemented with 30 sxs Clas	A H
2/14/04	Set Flug at 8440' to 8340', cemented with 30 sxs Clas	
	Set Plug at 7000' to 6900', cemented with 30 sxs Clas	
	Set Plug at 4700' to 4500', cemented with 60 sxs Clas	
	Set Fing at 4700 to 4500, cemented with 00 sxs clas	s n.
2/15/84	Ran 109 joints of 4 1/2" 10.5#, K-55 casing, set at 4	3851
2/15/04	Cemented with 200 sxs Class C Neat, displaced with 69 bbls	
	fresh water. Bumped plug at 1000#, held for 30 min.,	
	WOC 18 hrs.	here ok.
	Waiting on Completion unit.	
	nareing on compretion and	
hereby certify that th	e information above is true and complete to the best of my knowledge and belief.	
hereby certify that th		Iuno 12 1094
hereby certify that the	e information above is true and complete to the best of my knowledge and belief.	June 12, 1984
· Ianda	INAL SIGNED BY JERRY SEXTON	DATE June 12, 1984
. Janda		June 12, 1984



---