

NO. OF COPIES RECEIVED		
DISTRIBUTION		
AMOUNT FE		
FILE		
S.G.S.		
AND OFFICE		
PERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
		5. State Oil & Gas Lease No.
OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- DRY		7. Unit Agreement Name
Name of Operator <i>Natural Resource Management</i> <del>NRM Petroleum Corporation</del>		8. Farm or Lease Name Metzger
Address of Operator 600 W. Illinois, Suite 800 - Midland, Texas 79701		9. Well No. 7
Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>853</u> FEET FROM THE <u>East</u> LINE, SECTION <u>17</u> TOWNSHIP <u>7S</u> RANGE <u>34E</u> NMPM.		10. Field and Pool, or Wildcat Chaveroo (San Andres)
15. Elevation (Show whether DF, RT, GR, etc.) 4328.6 GR		12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
WELL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8 5/8" csg set @ 1649' w/750 sx cement (circ.) Completed 8-23-84.  
 4 1/2" csg set @ 4550' w/1600 sx cement.  
 Perfs from 4472' - 4484' 4 SPF (48 holes)

TIH open-ended to 4420'. Circ hole clean. Spot 20 sx Class "C" plug @ 4420'. TOH to 3000'.  
 WOC. Well on vacuum. Load hole w/30 bbls. Well on vacuum. TIH to 4420'. Spot 30 sx Class  
 "C". Pull 10 stands. SI 1 hr. TIH w/wireline and tag plug @ 4470'. WOC 1 hr. TIH and spot  
 10 sx plug (150') from 4420' to 4270'. TOH to 3000'. Spot 10 sx plug (150') from 3000' to  
 2850'. TOH to 1700'. Spot 10 sx plug (150') from 1700' to 1550'. TOH. Spot 10 sx plug  
 @ surface. TIH w/wireline between 4 1/2" and 8 5/8" csg. Tag cement @ 1625'. ND wellhead.  
 Weld plate on 8 5/8" csg. Well Plugged and Abandoned on 9-18-84. Plugging operations  
 commenced on 9-17-84.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>Mary Carlton</i> Mary Carlton	TITLE Production Secretary	DATE 9-24-84
APPROVED BY <i>Jack Griffin</i> Jack Griffin	TITLE OIL & GAS INSPECTOR	DATE AUG 16 '88

CONDITIONS OF APPROVAL, IF ANY: