Form 3160-5 (June, 1990) BUREAU OF L SUNDRY NOTICES Do not use this form for proposals to drill	TO STATES OF THE INTERIOR AND MANAGEMENT N.M. Oil Cons. AND REPORTS ON WELL 925 N. Frencl or to deepen or reentry to Hotobs, read oi88 PERMIT-" for such proposals	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 DIVISIOUSIGNATION and Serial No. DIMNM40624 6. If Indian, Allottee or Tribe Name 3240			
	N TRIPLICATE	7. If Unit or CA, Agreement Designation			
 Type of Well Oil Gas Well Well Well Other Name of Operator Novy Oil & Gas, Inc. Address and Telephone No. 125 N. MARKET ST., SUITE 1230, WICHITA, K 		8. Well Name and No. OPTION FEDERAL 5 9. API Well No. 30-041-20767 10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey Desc 660 FWL & 1980 FSL SEC. 35 - T8S	VADA PENN 11. County or Parish, State ROOSEVELT, NEW MEXICO				
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
	TYPE OF ACTION				
Notice of Intent X Subsequent Report Final Abandonment Notice	X Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well			
give subsurface locations and measured and true vert 6/30/00 MIRU - move in workstring. PC POOH w/remaining tbg. & pkr.	I pertinent details, and give pertinent dates, including estimated date of sta cal depths for all markers and zones pertinent to this work)* OH w/40 stands tubing. Close in for vac. TIH w/gauge ring - set down @ 1100'. Call Peter C				
Continue TIH - total 258 jts. tub	^{7/10/00} bottom. Mr. Chester agreed. TIH w/173 jts. tubing. Close in well. Continue TIH - total 258 its. tubing. Set down @ 7988'. Spot 70 sx. from 7988' to 7399'. Tag plug @ 7399' - approved by Pe				
7/12/00 Circulate mud to surface. Spot					
7/13/00 Pull & lay down 4121' of 5 1/2"	3/00 Pull & lay down 4121' of 5 1/2" casing. TIH w/tubing to 4185' & spot 75 sx. cement. WOC.				
Peter Chester. Perf 8 5/8" casi	Tag top plug @ 3844' Spot 35 sx, cement from 2015' to 1881' Dug out wellhead. Cement @ surface on 8 5/8" casing. Call				
	Lishiity and	to plugging of the well Bas. ar bond is retained until orntion is completed.			
14. I hereby certify that the foregoing is true and correct Signed	Young Title PRESIDENT	Date 7/27/00			
(This space for Federal or State office use)	SERICI ELINI ENGI	NEER Date SEP 2 8 2000			
Conditions of approval, if any:	knowingly and willfully to make any department or agency of the U	nited States any false, fictitious or fraudulent statements			

or representations as to any matter within its jurisdiction.

Z	,	1.1	\mathbf{v}
~	~ .	ΠQ.	44

đ,





MAYO MARRS CASING PULLING INC. BOX 863 KERMIT, TEXAS 79745

NOVY OIL & GAS, INC.

Lease: OPTION FEDERAL # 5 Project: P & A – CEMENTING REPORT

7-11-2000 – SPOT 70 SXS @ 7988'-7399' – TAGGED – OK'D BY PETE CHESTER 7-12-2000 - PULLED 4121' OF 5 ½" CASING 7-12-2000 – SPOT 30 SXS @ 4961'-4673' 7-13-2000 - SPOT 75 SXS @ 4185'-3844' TAGGED 7-14-2000 - SPOT 35 SXS @ 2015'-1881' 7-14-2000 - SPOT 65 SXS @ 558'-302' –PERF. COULD NOT PUMP INTO PERFS 7-14-2000 - SPOT 15 SXS @ 50'- SURFACE

INSTALL DRY HOLE MARKER CIRCULATE 10# MUD





MAYO MARRS CASING PULLING INC.

NOVY OIL & GAS, INC.

ATTN: MIKE NOVY Lease: OPTION FEDERAL # 5 Project: P & A

FAX 316-265-2008

06-30-00

NOTIFY BLM - MIRU - NUBOP - POOH WITH 40 STANDS - CLOSE IN FOR VACATION

7-10-00

POOH WITH REST OF TUBING & PACKER – RIH WITH GAUGE RING & SET DOWN @ 1100' – CALL PETE CHESTER WITH BLM & MIKE NOVY – AGREE TO SPOT CEMENT PLUG – RIH WITH 173 JOINTS TUBING – CLOSE IN WELL

7-11-00

RIH & STACK OUT @ 7988' – CALL PETE CHESTER BLM – OK SET PLUG – SPOT 70 SXS @ 7988' - POOH – WOC – TAG PLUG @ 7399' – CIR. 10# MUD – POOH TO 4961' – CLOSE IN WELL

7-12-00

CIR. MUD TO SURFACE – SPOT 30 SXS @ 4961'-4673' – POOH – WELD ON PULL NIPPLE – TAKE STRETCH - - CUT CASING @ 4121' – WORK CASING LOOSE –

7-13-00

LAY DOWN 99 1/2 JOINTS CASING - RIH & SPOT 75 SXS @ 4185' - POOH - WOC

7-14-00

RIH & TAG CEMENT @ 3844' – POOH & SPOT 35 SXS @ 2015'-1881' – POOH – DIG OUT WELLHEAD – DISCOVER CEMENT @ SURFACE ON 8 5/8" CASING – CALL BLM PETE CHESTER - PERF. @ 500' – RUN 8 5/8" PACKER COULD NOT PUMP INTO PERFS – CALL BLM – LAY DOWN PACKER – RIH & SPOT 65 SXS @ 558'-302' – POOH & SPOT 15 SXS @ 20' TO SURFACE - CUT OFF WELLHEAD – LEVEL PIT & CELLAR – MOVE OUT



. V .