Form 3160-5 (June, 1990)

U' TED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

À.	Oil	Cras.	Divisi	OR FORM APPROVED Budget Bureau No. 1004-0135
			.	Budget Bureau No. 1004-013
525	N.	Fre.ic	n Ur.	Expires: March 31, 1993

Hobbs. NM 88240 ease Designation and Serial No.

	IVIVI	oo.	2 4 613	
0000,		~~	NAI	NM40624
			1.41491	TITLE TOUL

		NWINW40024
SUNDRY NOTICES AN Do not use this form for proposals to drill or Use "APPLICATION FOR PI		6. If Indian, Allottee or Tribe Name
SUBMIT IN	7. If Unit or CA, Agreement Designation	
1. Type of Well Oil Gas Well Well Other		8. Well Name and No.
Well Other 2. Name of Operator		OPTION FEDERAL 5
Novy Oil & Gas, Inc.		9. API Well No.
3. Address and Telephone No.		30-041-20767
125 N. MARKET ST., SUITE 1230, WICHITA, KS 6	7202 (316) 265-4651	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Descript	ion)	VADA PENN
660 FWL & 1980 FSL SEC. 35 - T8S - F	35E	11. County or Parish, State ROOSEVELT, NEW MEXICO
12. CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, REP	ORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTI	ON
X Notice of Intent	X Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
<u></u>	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other	Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

- 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work)*
- 1. MIRU MOVE IN WORKSTRING.
- 2. SET CICR @ 7780' SQZ. 100 SXS BELOW SPOT 15 SXS ON TOP.
- 3. CIR. 9.5# MUD
- 4. SPOT 25 SXS @ 4950' 4750'
- 5. SPOT 45 SXS @ 4150' 4050' PERF & SQZ OR PULL 5 1/2 CASING.
- 5A. SPOT 40 SXS @ STUB IF CASING PULLED FROM DIFFERENT DEPTH.
- 6. SPOT 35 SXS @ 2000' 1900' TOP OF SALT
- 7. SPOT 65 SXS @ 500' 400' PERF OR PULL 8 5/8 CASING.
- 7A. SPOT 65 SXS @ STUB IF CASING PULLED FROM DIFFERENT DEPTH
- 8. SPOT 15 SXS @ SURFACE
- 9. CUT OFF WELLHEAD & ANCHORS COVER PIT INSTALL DRY HOLE MARKER MOVE OUT

Signed Frank E. Howy	Title	PRESIDENT Date	2/16/00
(This space for Federal or State office use) (OPIC: SGD.) DAVID R. GLASS Approved by	Title	PETROLEUM ENGINEER	FEB 2 5 2000
Conditions of approval, if any:			

or representations as to any matter within its jurisdiction.

BUREAU OF LAND MGMT. BOSIVELL OFFICE

MECEINED