

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P.O. Box 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG-3640	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER Dry hole	7. Unit Agreement Name
2. Name of Operator Read & Stevens, Inc.			8. Farm or Lease Name DAVID STATE
3. Address of Operator P.O. Box 1518, Roswell, NM 88201			9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>East</u> LINE AND <u>660</u> FEET FROM THE <u>South</u> LINE. SECTION <u>32</u> TOWNSHIP <u>7S</u> RANGE <u>35E</u> NMPM			10. Field and Pool, or Wildcat Wildcat
5. Elevation (Show whether DF, RT, GR, etc.) 4237.1' GL			12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		
OTHER	<input type="checkbox"/>		

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>		
OTHER	<input type="checkbox"/>		

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-11-85 Trip out w/rods & tbg, LD rods, set CIBP @ 4400', SDON.

7-12-85 Trip in w/tbg, spot 3sx cmt on top of CIBP, 35', circ hole w/salt gel mud, cut csg @ 2900', LD 48jts, SDON.

7-13-85 2950', spot 75sx Class "C" cmt half in & half out of csg stub, 8 5/8" csg shoe @ 1735', spot 45sx Class "C" @ 1785', wait 4hrs, trip in w/tbg, tag @ 1732'.

7-14-85 Spot 40sx Class "C" @ 1732', wait 4hrs, trip in w/tbg, tag @ 1578', spot 15sx, plug @ surface 0-30', Install dry hole marker, cut off anchors, prep to clean loc & prep for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. D. Stubb TITLE Drilling and Production Manager DATE 7-15-85

APPROVED BY Ronald M. Cantelero TITLE OIL & GAS INSPECTOR DATE JAN 17 1986

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 16 1985

1985 JUL 16