

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

IL CONSERVATION DIVISIC
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- <u>PXA</u>	7. Unit Agreement Name
2. Name of Operator <u>AMOCO PRODUCTION COMPANY</u>	8. Farm or Lease Name <u>Amsworth</u>
3. Address of Operator <u>P. O. BOX 68 HOBBS, NEW MEXICO 88240</u>	9. Well No. <u>1</u>
4. Location of well UNIT LETTER <u>A</u> <u>853</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>4</u> TOWNSHIP <u>8-S</u> RANGE <u>36-E</u> NMPM.	10. Field and Pool, or Wildcat <u>Wildcat Fusselman</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4122.6' GL</u>	12. County <u>Roosevelt</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CAS NG TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled with a 8 3/4" bit to a TD of 11,331'. Received verbal approval from Mr. Jerry Sexton to PXA the subject well. PXA'd as follows: (Class Cement used for all plugs)
Plug #1 - 505X from 11321' - 11221'.
Plug #2 - 455X from 11008' - 10908' - Top of Fusselman at 10958'.
Plug #3 - 605X from 8300' - 8200' - Across top of Abc.
Plug #4 - 605X from 6200' - 6100'.
Plug #5 - 505X from 4050' - 3950' across intermediate casing shoe.
Plug #6 - 355X from 2300' - 2200' across top of the salt.
Plug #7 - 105X from 15' to surface. Installed PXA marker. Rig released 1-3-86.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles M. Serrano

TITLE ADMINISTRATIVE ANALYST (SG)

DATE 1/7/86

APPROVED BY Jack Griffin

TITLE OIL & GAS INSPECTOR

DATE JAN 13 1989

CONDITIONS OF APPROVAL, IF ANY: