

N. M. OIL CONS. COMMISSION

P. O. BOX 1980

Form 3160-5
(November 1983)
(Formerly 9-331)

UNITED STATES HOBBS, NEW MEXICO, 88240
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
NM-57710

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
MWJ 34 Federal

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Vada (Penn)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec 34, T-8S, R-36E

12. COUNTY OR PARISH
Roosevelt

13. STATE
New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

MWJ PRODUCING COMPANY

3. ADDRESS OF OPERATOR

400 W. Illinois Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FNL & 1340' FWL Sec 34

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4084' GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) to run intermediate csg ☒
REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11/25/87: Drilled to 4175'. RU & ran 100 jts 8-5/8" 24#, 28# & 32# J-55 csg w/insert float in top of 1st jt & 3 centralizers. RU Howco & brk circ, wshd 8' to btm & circ 30 min. Cmt'd w/1300 sx Howco Lite w/15# salt, 5# gilsonite & 1/4# flocele followed by 200 sx Premium w/2% CaCl-2. PD @ 2: AM 11/26/87. Chk'd float, held OK. WOC 12 hrs. Tstd csg to 1000 psi, OK. 300+ circ.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Pat Drexler - Agent

DATE 11/30/87

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

