

ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

POST OFFICE BOX 1980 HOBBS, NEW MEXICO 88241-1980 (505) 393-6161

April 25, 1997

Saga Petroleum Limited Liability Company 415 West Wall, Suite 835 Midland, Texas 79701

Re: Todd Lower San Andres Unit Test Results

Gentlemen:

An Oil Conservation Division representative recently witnessed bradenhead tests on the active injection wells in your Todd Lower San Andres Unit.

It is noted that a unit was on Well No. 11 located in Unit K of Section 29, Township 7 South, Range 36 East, for a workover procedure. We request that you submit a subsequent sundry notice with the information outlining the work performed. Since this is a federal well, please complete the BLM form, and send a "complimentary" copy and the original chart to this office.

Well No. 15 located in Unit O of Section 29, Township 7 South, Range 36 East, failed to demonstrate mechanical integrity. As required by the EPA, we request that you shut in this well until such time as repairs are made and approved.

We are enclosing a copy of the test sheet for your information.

We request 24 hours notice prior to repairs in order to witness the operation and the pressure test upon completion of repairs.

Very truly yours

OLL CONSERVATION DIVISION

Jerry Sexton

Jerry Sexton Supervisor, District I

JS:bp

cc: William J. LeMay File

Enclosure

OPERATOR LEASE : POOL :	SAGA PETR TODO LOWE	C	うだいやう おりかい シー・アイ	after a state attraction and search search	ON DIVISION TEST	ЗИ-ИЦ(-2к)(-, ИЕЦ н (*
FCOTAGE ORDER NO	1980-E .wFx571	PRESS LM	T 110	Ø TYPE LEA Date int	SE F REGAN	S RANGE 36 E Type Well 6
OPERATOR CASING	Elo-Apr-90) TEST TYP UYLAN SET AT	E BHT TOP CM	PASS/FAT OCD REP:	L BIO2 TURNACLIFF PRESSURE Ø	REMARKS
INTERM-1 INTERM-2 PROD	4 1/2	- - 433		3005×	Q	n n
LINER	-	-			* *	n
TUBING	2 3/8	412	4 PKR		VAC	u
	ETTER DATE			DATE	REPAIR	SNC NO
DEST DATE DEERATOR CASING	REP:	TEST TYPE MARK MLAI	E PT DENKA TOP CMT	PASS/FAIL OCD REP: CEMENTED	PINO2 NOT WITNESS PRESSURE Ø	ED REMARKS
NTERM-1 NTERM-2 'ROD	u	- - 4336	NDB	- - 3008X	• •	
INER	11		n	17		
UBING	2 3/8	4124	PKR		0	
EMARKS: Epair le	INFORMATIC TTER DATE	N ON TEST	SUBMITT	ED BY OPER DATE I	ATOR REPAIR ,	SNC NO
EST DATE PERATOR	04-16-97 REP: Uy SIZE	TEST TYPE		PASS/FAIL OCD REP:	Jan	
URFACE (8 5/8	SET AT 329	TOP CMT NDB	CEMENTED 2505X	PRESSURE P	(EMARKS
VTERM-1 VTERM-2			" h	-	-1447-04-04-04-04-04-04-04-04-04-04-04-04-04-	
	4 1/2	4330	NDB	300SX	0 - Ma	tes Igolt
INER . Jeing ;	· 2 3:79	4124	* ****	24		-
				REPAIRED	0 Shut	en - bal BNC ec - Juliy curut
			4 300 323 520 530 540 540 551 551 555 555	apparent	they tubing he	- hole -