

UNITED STATES N. M. OIL CONS. COM. 1980
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
RIO BOX 1980
HOBBS, NEW MEXICO 88240

Form approved.
Budget Bureau No. 1004-0.35
Expires August 31, 1985
5. LEASE DESIGNATION AND SERIAL

NM 69680

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR H. L. Brown, Jr.	8. FARM OR LEASE NAME Federal "28" A Com
3. ADDRESS OF OPERATOR Post Office Box 2237, Midland, Texas 79702	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit A 660 660' FNL & 660' FEL of Sec 28, T 7S, R 37E, Unit A	10. FIELD AND POOL OR WILDCAT North Bluit (Siluro Devonian)
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 28, T 7S, R 37E	12. COUNTY OR PARISH Roosevelt
13. STATE NM	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4062.6 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

H. L. Brown, Jr. has plugged and abandoned the Federal "28" A Com #1 well. Below recaps the procedure used.

Began plugging operations on 4-12-91.

1. Set CIBP @ 8050'. Dumped 35' cement on top.
2. Circulated hole with 9.5 ppg mud.
3. Set CIBP @ 5635'. Dumped 35' cement on top.
4. Cut and pulled 4 1/2" casing from 5005' - 5000' casing laid down.
5. Spotted 50 sx cement @ 5075'. Tagged TOC @ 4850'.
6. Set 8 5/8" CIBP @ 3850'. Dumped 35' cement on top.
7. Spotted 30 sx cement @ 575'.
8. Spotted 15 sx cement @ 60'.
9. Welded on cap.

Well P&A'd 4-16-91

18. I hereby certify that the foregoing is true and correct

SIGNED Mark A. Gosch TITLE Production Engineer

DATE 5-30-91

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____
Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side

APPROVED
DATE PETER W. CHESTER
JUN 5 1991
BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

RECEIVED

JUN 06 1991

CCC
MOSES OFFICE