Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Revised March 25, 1999 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 District II 30-005-00478 OIL CONSERVATION DIVISION 811 South First, Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE 1000 Rio Brazos Rd., Aztec, NM 87410 FEE XXX Santa Fe, NM 87505 District IV State Oil & Gas Lease No 1220 S. St. Francis Dr., Santa Fe, NM SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH Jennings Com #1 PROPOSALS.) 1. Type of Well: Oil Well XXGas We□ Other 2. Name of Operator Well No. Primero Operating, Inc. Address of Operator 9. Pool name or Wildcat PO Box 1433, Roswell, NM 88202-1433 Well Location feet from the South line and 660 feet from the West Unit Letter M: 660 Section Township 8S Range 30E **NMPM** Chaves County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4036.8 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND **ABANDONMENT** PULL OR ALTER CASING MULTIPLE CASING TEST AND **CEMENT JOB** COMPLETION OTHER: OTHER: Perforate and Plug Back XXXX 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 5/29 to 6/1/2001: Perforated 3236-42, 48-58, 98-3300' w/1 spf and acidized with 2500 gals 20% acid. Swabbed unlimited amount of water, Clorides approximately 44,000 ppm. 6/2 to 6/5/2001: Perforate 3050-56, 3118-22, 34-36, 68-72, 88-91 w/ 2 spf. Set RBP at 3213' and acidized well w/ 2500 gallons 20% acid. Swabbed unlimited amount of water. Move RBP up to 3150' and made one swab run then well kicked off flowing gas. 6/6 to 6/9/2001: Killed well and Pulled RBP. RIH and set CIBP @ 3152'. RIH open ended and made one swab run to kick well off. Well started flowing to pit. SI well waiting on pipeline connection. I hereby certify-that the information above is true and complete to the best of my knowledge and belief. **SIGNATURE** TITLE President DATE 6/11/01 Type or print name Phelps White Telephone No. 505-622-1001 (This space for State use) Paul Kautz APPPROVED BY TITLE DATE Geologist Conditions of approval, if any: