

P. C. BOX 1980

HOBBS, NEW MEXICO 8240

(Other instructions on reverse side)

Form 3160-5
(November 1983)
(Formerly 9-331)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTForm approved.
Budget Bureau No. 1004-0115
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-32409

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)1. OIL ☒ WELL GAS ☐ WELL OTHER ☐

CONFIDENTIAL

2. NAME OF OPERATOR

McClellan Oil Corporation

3. ADDRESS OF OPERATOR

P.O. Drawer 730, Roswell, N.M. 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

660 FNL & 330 FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4012' D.F.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Sam Fed.

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 28-T15S-R30E

12. COUNTY OR PARISH 13. STATE

Chaves

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7/30/87 Ran CIBP to 9615'. Dumped 2 sx. cement on plug.

7/31/87 Perfed 8748' to 8830' w/22 holes total. Acidized w/100 gals 15% MCA acid. Swab Tested. Producing Formation Water.

8/4/87 Set CIBP at 8710'. Dumped 2 sx. cement on plug.
Perfed 8534' to 8627'. Acidized w/2000 gals 15% MCA acid.
Swab Tested w/good gas & oil show.

8/14/87 Straddled 8534' to 8540'. Acidized w/1500 gals 20% NEFE acid.

8/18/87 Straddled 8596' to 8627'. Acidized w/1500 gals 20% NEFE acid.

Straddled 8567' to 8569'. Acidized w/3000 gals 20% NEFE acid.

8/21/87 Swab Tested all zones. Swab w/good oil & gas.

9/1/87 Pulled packer and bridge plug. Ran tubing, pump & rods.

9/4/87 Put on Pump.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Operations Manager

DATE 9/9/87

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
PETER W. CHESTER
DATE

SEP 14 1987

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side