

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE  
(Other instructions  
reverse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0338-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Peery Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Little Lucky Lake Devonian

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 29, T-15-S, R-30-E

12. COUNTY OR PARISH 13. STATE

Chaves

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

TEXACO Inc.

3. ADDRESS OF OPERATOR

P.O. Box 728 - Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surfaceWell is located 660' from the South line and 1980' from the  
East line of Section 29, T-15-S, R-30-E, Unit Letter O,  
Chaves County, New Mexico.

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3955' (DF)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☒SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

The following work has been completed on subject well:

1. Pull pumping equipment.
2. Perforate 7" casing w/1 JSPF from 10,959' to 10,965' and 10,983' to 10,988'.
3. Run 2-3/8" tubing w/packer and set @ 10,890' w/tail pipe to 11,005'.
4. Acidize w/6,000 gals. 26% NEA in 3 equal stages. Separate stages w/75" Unibeads. Follow each stage w/50 bbls treated water.
5. Swab, ran pumping equipment, test and return to production.

RECEIVED

MAR 24 1970

U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

RECEIVED

MAR 25 1970

U. S. G.

ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Assistant District

Superintendent

DATE March 23, 1970

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD PURPOSES  
MAR 23 1970  
Date  
ACTING District Engineer

\*See Instructions on Reverse Side