

Form 9-331  
(May 1963)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE  
(Other instructions  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

|                                                                                                                                                                                                   |  |                                                                    |                                |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--------------------------------------------------------------------|--------------------------------|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>                                                                                  |  | 5. LEASE OR WELL NO.<br><b>S. Caprock Queen Unit</b>               |                                |
| 2. NAME OF OPERATOR<br><b>Union Oil of California</b>                                                                                                                                             |  | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME<br><b>Chaves County, N.M.</b> |                                |
| 3. ADDRESS OF OPERATOR<br><b>500 N. Maricopa - Midland, Texas</b>                                                                                                                                 |  | 7. UNIT AGREEMENT NAME<br><b>S. Caprock Queen Unit</b>             |                                |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br><b>1980 PSL, 660 PSL, Sec. 5, Twp. 15 S, Rng. 31 E</b> |  | 8. FARM OR LEASE NAME<br><b>S. Caprock Queen Unit</b>              |                                |
| 14. PERMIT NO.                                                                                                                                                                                    |  | 9. WELL NO.<br><b>12 - Tr. 11</b>                                  |                                |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.)<br><b>GL 4461</b>                                                                                                                                  |  | 10. FIELD AND POOL, OR WILDCAT<br><b>S. Caprock Queen Unit</b>     |                                |
|                                                                                                                                                                                                   |  | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA<br><b>Sec 5</b>   |                                |
|                                                                                                                                                                                                   |  | 12. COUNTY OR PARISH<br><b>Chaves</b>                              | 13. STATE<br><b>New Mexico</b> |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Plugging Procedures Below:

1. 10 3/4" @ 307' @ 225 Sx.

2. 9 1/2" @ 3163' @ 575 Sx.

3. Perf. @ 3113' - 3120'

Plug #1 - 25 Sx. @ 3100'

Plug #2 - 5 Sx. @ Surface

Recovered 3000' Tubing

Establish Dry Hole Marker

RECEIVED

AUG - 4 1971

U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

H. D. Oden, Inc.

18. I hereby certify that the foregoing is true and correct

Agent for Union Oil  
of California

SIGNED

TITLE

DATE

August 11, 1971

(This space for Federal or State office use)

APPROVED

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

AUG 29 1971

H. L. BEEKMAN  
ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.