

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
LC 0647.0	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator		5. Caprock Queen Unit	
3. Address of Operator		8. Farm or Lease Name	
500 N. Wartenfield - Midland, Texas		5. Caprock Queen Unit	
4. Location of Well		9. Well No.	
UNIT LETTER <u>U</u> , <u>66</u> FEET FROM THE <u>W</u> LINE AND <u>66</u> FEET FROM		10. Field and Pool, or Wildcat	
THE <u>N</u> LINE, SECTION <u>6</u> TOWNSHIP <u>15 S</u> RANGE <u>81 E</u> NMPM.		5. Caprock Queen Unit	
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	
61. 4461		Chaves	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedures Below:

1. 5/8" - 3" - 1/12" ex.
2. 7" - 3120' - 1/12" ex.
3. Perf. - open 3115 - 3120'
- Plug #1 - 12" plug @ perf.
- Plug #2 - 10" plug @ Stub of 7"
- Plug #3 - 10" plug in and out of surface
- Plug #4 - 2" plug @ surface

Establish Dry Hole Marker

H. W. Uden, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>H. W. Uden</u>	TITLE <u>Agent for Union Oil of California</u>	DATE <u>June 8, 1971</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT 1</u>	DATE <u>JUN 28 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

3-5388

RECEIVED

JUN 21 1971

OIL CONSERVATION COMM.
HOBE, N. M.