

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input checked="" type="checkbox"/>

5. State Oil & Gas Lease No.
LC 004900

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	2. Caprock Queen Unit
3. Address of Operator	8. Farm or Lease Name
5. H. Marrenfeld - Midland, Texas	2. Caprock Queen Unit
4. Location of Well	9. Well No.
UNIT LETTER <u>U</u> , <u>990</u> FEET FROM THE <u>5</u> LINE AND <u>2310</u> FEET FROM	10. Field and Pool, or Wildcat
THE <u>2</u> LINE, SECTION <u>8</u> TOWNSHIP <u>15 S</u> RANGE <u>31 E</u> NMPM.	Caprock Queen Unit
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
OL 4443'	Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedures Below:

1. 5/10 - 317' w/15' ex.
 2. 6' 315' w/15' ex.
 3. Perf. to 3124' - 3132'
- Plug #1 - 10' plug to perf.
- Plug #2 - 100' plug to stub of 6"
- Plug #3 - 10' plug in and out of surface
- Plug #4 - 20' plug to surface

Establish Dry Hole Marker

H. L. Uden, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Agent for Union Oil of California</u>	DATE <u>June 8, 1971</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT 1</u>	DATE <u>JUN 28 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JUN 23 1971

OIL CONSERVATION COMM.
HOBBS, N. M.