

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p> <p>5. State Oil & Gas Lease No. Patent</p>
<p>1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p> <p>2. Name of Operator Union Oil of California</p> <p>3. Address of Operator 500 N. Marienfeld - Midland, Texas</p> <p>4. Location of Well UNIT LETTER F 1980 FEET FROM THE N LINE AND 1980 FEET FROM THE N-W LINE, SECTION 8 TOWNSHIP 15 S RANGE 31 E NMPM.</p>		<p>7. Unit Agreement Name S. Caprock Queen Unit</p> <p>8. Farm or Lease Name S. Caprock Queen Unit</p> <p>9. Well No. T-63, W-6, Sec. 8</p> <p>10. Field and Pool, or Wildcat S. Caprock Queen Unit</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) GL 4451</p>		<p>12. County Chaves</p>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedures Below:

1. 8 5/8" @ 338' W/235 Sx.
2. 5 1/2" @ 3112' W 175 Sx.
3. Perf. @ Open Hole 3112' - 3122'

Plug #1 - 25 Sx. @ 3100'
Plug #2 - 5 Sx. @ Surface

Recovered 3000' Tubing

Establish Dry Hole Marker

H. D. Oden, Inc.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>H. D. Oden</i>	TITLE Agent for Union Oil of California	DATE May 8, 1972
APPROVED BY <i>John W. Runyan</i>	TITLE <i>[Signature]</i>	DATE <i>175</i>

CONDITIONS OF APPROVAL, IF ANY: