

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. Patent
7. Unit Agreement Name S. Caprock Queen Unit
8. Farm or Lease Name S. Caprock Queen Unit
9. Well No. T-63, W-9, Sec. 8
10. Field and Pool, or Wildcat S. Caprock Queen Unit
12. County Chaves

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name S. Caprock Queen Unit
2. Name of Operator Union Oil of California	8. Farm or Lease Name S. Caprock Queen Unit
3. Address of Operator 500 N. Marienfeld - Midland, Texas 79701	9. Well No. T-63, W-9, Sec. 8
4. Location of Well UNIT LETTER I 2310 FEET FROM THE S LINE AND 990 FEET FROM E 8 15 S 31 E THE LINE, SECTION TOWNSHIP RANGE NMPM.	10. Field and Pool, or Wildcat S. Caprock Queen Unit
15. Elevation (Show whether DF, RT, GR, etc.) GL 4445	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedures Below:

1. 8 5/8" @ 280' W/200 Sx.
2. 5 1/2" @ 3200 W/175 Sx.
3. Perf. @ 3150' - 3162'

Plug #1 - 25 Sx. @ 3100'
Plug #2 - 5 Sx. @ Surface

Recovered 3000' Tubing

Establish Dry Hole Marker

H. D. Oden, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED H. D. Oden	TITLE Agent for Union Oil of California	DATE May 8, 1972
APPROVED BY John W. Runyan	TITLE [Signature]	DATE 10
CONDITIONS OF APPROVAL, IF ANY:		